

Before Frauscher Wheel Sensors Were Installed at Two Sites



1572 Trains



150 Integrity Failures - Axle Miscounts

After Frauscher Wheel Sensors Were Installed at Two Sites



2272 Trains

0 Integrity Failures - Axle Miscounts