
21-600 HANOVER PINEHILLS II

Weekly Site Photos Week Ending 5/19/2023



Sitework

Grading at Avalon gate



Building 1 Exterior

Exterior siding is ongoing



Building 1 Exterior

Exterior siding is ongoing




Building 1A Interior

Top — level 4 with gypcrete

Bottom left — level 3 insulation started

Bottom right — level 2 MEP ongoing







Building 1B Interior

Top — level 4 MEP started

Bottom left — level 3 MEP started

Bottom right — level 2 MEP started








Clubhouse

Framing with MEP ongoing










Clubhouse

Corridor framing and MEP rough started



Building 2 Exterior

Exterior painting is ongoing



Building 2 Interior

Top left – level 4

Top right – level 3

Bottom left – level 2

Bottom right – level 1











Building 2 Interior

Level 3 corridor carpet installation started



HANOVER