

2.0 Executive Summary

Criterion's Project #: 200204
 ULCS #: 2140
 Control Number: 2020214003.1
 Work Order Number: 1828497, 1836126, 1836126, 1836126, 1794407 & 1794416
 School Name: Masterman Middle/High School
 Site Address: 1699 Spring Garden Street
 Project Dates: January 11 – January 15, 2020
 Criterion's Project Monitor: Mr. Paul Scally, Ms Lauren Pickett and Mr. Sam Oseroff
 Criterion's Project Manager: Mr. Ian Forster

The asbestos abatement project involved the removal or repair of the materials listed below:

Location	Material	Quantity Removed or Repaired
Room 101	Pipe Insulation	1 Linear Foot (LF) Repaired
Room 104	Pipe Insulation	1 LF Repaired
Room B-14	Pipe Insulation	2 LF Repaired
Room B-10	Pipe Insulation	<1 LF Repaired
Room 201	Pipe Insulation	1 LF Repaired
Room 203	Pipe Insulation	1 LF Repaired
Room 207	Pipe Insulation	1 LF Repaired
Room 202	Pipe Insulation	1 LF Repaired
Room 211	Pipe Insulation	1 LF Repaired
Room 209	Pipe Insulation	1 LF Repaired
Room 307	Pipe Insulation	1 LF Repaired
Room 311	Pipe Insulation	1 LF Repaired
Room 309	Pipe Insulation	1 LF Repaired
Nurses' Room	Plaster – Screw holes in wall	<1 Square Foot (SF) Repaired
Building Engineer Room	Pipe Insulation	1 LF Repaired
Room 9	Pipe Insulation	1 LF Repaired
Room 302	Pipe Insulation	1 LF Repaired
Room 304	Pipe Insulation	1 LF Repaired
Room 313	Pipe Insulation	1 LF Repaired
Room 309	Pipe Insulation	1 LF Repaired
Room 313	Pipe Insulation	1 LF Repaired
Room 303	Pipe Insulation	1 LF Repaired
Room 305	Pipe Insulation	1 LF Repaired
4 th Floor Teacher's Lounge	1x1 Acoustical Ceiling Tile	5 SF Removed
Room 406	Pipe Insulation	<1 LF Repaired
Room 410	Pipe Insulation	<1 LF Repaired