



Industry: Property Management
Structure: Multi-Residential
Square Footage: 1,100
Type of Loss: Mold

• Brief Scope: A small, undetected water leak behind the dishwasher led to mold development on the back wall of the cabinet space in this kitchen. The apartment staff requested that the counter top remain in place due to the unavailability of replacement laminate. SERVPRO® carefully removed the faces of the cabinets for later reuse, braced and supported the counter tops, and collapsed the cabinet boxes. Drywall behind the cabinets was removed and wet studs were dried. Mold was then contained and removed. After mold mitigation, reconstruction was done on the drywall and cabinets under the counter tops. The cabinets were refaced with the original drawer fronts and drawers, leaving it "Like it never even happened."





Industry: Government

Structure: Prison – El Paso, TXSquare Footage: 275,000+

Type of Loss: Mold

• Brief Scope: This 11 story prison in downtown El Paso, TX had mold throughout various areas on

• each level. SERVPRO® completed the full mold remediation with clearance tests in 17 days. The cost savings were in the millions of dollars due to the timing of the project completion.



• Industry: Education

Structure Location: Minot, NDSquare Footage: 190,000+

Type of Loss: Mold

• Brief Scope: Multiple SERVPRO® agencies were called in to complete major muck-out, drying and cleanup due to historic 1000 year flooding in Minot, ND. Services ranged from a complete 3' muck-out of a 100,000 square foot high school to mold remediation of affected contents due to secondary damage.



Industry: Government

• Structure Correctional Facility, Milton, FL

Square Footage: 140,000+

• Type of Loss: Mold

• Brief Scope: This facility was totally consumed by mold growth as a result of the roof being compromised. Mold was remediated over a six month timeframe and passed clearance testing on initial test.

