

A close-up photograph of a male mechanic with a beard, wearing a dark grey jacket, leaning over and working on a car's front wheel. The wheel is mounted on a blue lift. The background is slightly blurred, showing a workshop environment.

Answer B is correct

The pulsation caused by excessive front rotor runout is felt more in the steering wheel. Distorted or “warped” rear rotors are felt mostly in the seat.