






Product Safety Recall

HEAD recalls

13.03.2026

HEAD ski boots to replace Fluorescent yellow boot sole pads

Article code	Model name	Production years	
605048	VECTOR RS	2015	
606052	VECTOR EVO XR	2016 2017	
606035	VECTOR EVO ST	2016	
606115	ADVANT EDGE 95	2016	
601105	FORMULA 130 RS	2021	
601140	FORMULA 130		

Product Safety Recall

HEAD recalls HEAD ski boots

13.03.2026

to replace fluorescent yellow boot sole pads

HOW TO IDENTIFY THE MODELS

The model article code number consists of six digits and it is marked in the heel area on the inner side of the left boot



WHY IS THE PRODUCT BEING RECALLED?

The replaceable toe and heel pads (fluorescent yellow color) in the sole area can crack during normal use, which could affect the stability of the boot and increase risk of injury.

WHAT TO DO

- Stop using the product immediately.
- Contact HEAD using the details below to obtain replacement pads.

REMEDIES FOR CONSUMERS

If your boots are affected by this recall please contact HEAD. We will assist you in finding the most appropriate and fastest solution with free replacement pads and a visit to your HEAD Authorized Retailer who can assist you free of charge. Your bindings will need to be inspected and possibly readjusted after changing the pads.

CONTACT

Local assistance is provided by HEAD USA

Email: info@us.head.com Phone : 1-800-874-3235, option 3

We appreciate your understanding and apologies for any inconvenience caused

Spread the word about this recall with your family members and friends.

Conducted in cooperation with the US CPSC and Health Canada. Post until 12/2026.