



KNUCKLE HUBS

# NEW PRODUCT ANNOUNCEMENT

## New Part Numbers

Bulletin No. KHA072022

GSP North America is pleased to announce the immediate release of 15 New Knuckle Hub Assembly Part Numbers.



**IN STOCK &  
READY TO SHIP**



GSP #	DESCRIPTION
9692800	2004-06; Lexus ES330; (Front Right Knuckle Hub Assembly)
9692900	2008-17; Lexus RX350, RX450h / Toyota Highlander; (Front Right Knuckle Hub Assembly)
9693000	2008-17; Lexus RX350, RX450h / Toyota Highlander; (Front Left Knuckle Hub Assembly)
9693100	2004-07; Toyota Highlander; (Front Left Knuckle Hub Assembly)
9693200	2004-07; Toyota Highlander; (Front Right Knuckle Hub Assembly)
9693800	2007-11; Toyota Camry; (Front Left Knuckle Hub Assembly)
9693900	2007-11; Toyota Camry; (Front Right Knuckle Hub Assembly)
9694000	2007-12; Lexus ES350 / Toyota Camry; (Front Left Knuckle Hub Assembly)
9694100	2007-12; Lexus ES350 / Toyota Camry; (Front Right Knuckle Hub Assembly)
9694400	2004-10; Toyota Sienna; (Front Left Knuckle Hub Assembly)
9694500	2004-10; Toyota Sienna; (Front Right Knuckle Hub Assembly)
9695000	2008-12; Toyota Highlander; (Front Right Knuckle Hub Assembly)
9695100	2008-12; Toyota Highlander; (Front Left Knuckle Hub Assembly)
9695200	2011-17; Toyota Sienna; (Front Right Knuckle Hub Assembly)
9695300	2011-17; Toyota Sienna; (Front Left Knuckle Hub Assembly)

**QUALITY DRIVEN PERFORMANCE**

East Coast 2725 New Cut Road, Spartanburg, SC 29303

West Coast 950 N 119th Ave, Suite 100, Avondale, AZ 85323

864.578.6900

480.418.3405



[www.gspnorthamerica.com](http://www.gspnorthamerica.com)