



WHEEL HUBS

# NEW PRODUCT ANNOUNCEMENT

New Part Numbers

Bulletin No. WH072022



GSP North America is pleased to announce the immediate release of 109 New Wheel Hub Assembly Part Numbers.

**IN STOCK & READY TO SHIP**



GSP #	DESCRIPTION
101119B	2012-19; Buick Encore / Chevrolet Sonic, Spark EV, Trax; (Front & Rear Wheel Bearing)
531112B	2010-20; Fiat 500, 500X / Nissan Versa, Versa Note; (Front Wheel Bearing)
273511B	2009-19; BMW 528i, 528i xDrive, 535d, 535d xDrive, 535i, 535i GT, 535i GT xDrive, 535i xDrive, 550i, 550i GT, 550i GT xDrive, 550i xDrive, 640i, 640i Gran Coupe, 640i xDrive, 640i xDrive Gran Coupe, 650i, 650i Gran Coupe, 650i xDrive, 650i xDrive Gran Coupe, 740i, 740Ld xDrive, 740Li, 740Li xDrive, 750i, 750i xDrive, 750Li, 750Li xDrive, 760Li, ActiveHybrid 5, ActiveHybrid 7, Alpina B6 xDrive Gran Coupe, Alpina B7, Alpina B7 xDrive, Alpina B7L, Alpina B7L xDrive / Rolls-Royce Ghost, Wraith; (Rear Wheel Bearing Module)
483432B	2003-19; Mercedes-Benz C63AMG, CL550, CL600, CL63 AMG, CLS400, CLS55 AMG, CLS550, CLS63 AMG, CLS63 AMG S, E250, E280, E300, E320, E350, E400, E500, E55 AMG, E550, E63 AMG, E63 AMG S, GLK 250, GLK350, S350, S400, S450, S550, S600, S63 AMG, SL400, SL450, SL550, SL63 AMG, SL65 AMG; (Rear Wheel Bearing Module)
272044B	2006-13; BMW 1 Series M, 135i, 135is, 325xi, 328i, 328i xDrive, 328xi, 330i, 330xi, 335d, 335i, 335i xDrive, 335is, 335xi, M3; (Rear Wheel Bearing)
667003B	1992-06; Saab 9-2X / Subaru Impreza, SVX; (Rear Inner Wheel Bearing)
534244B	1990-96; Infiniti Q45 / Nissan 300ZX; (Front Wheel Bearing)
110017B	1991-03; Ford Escort / Mercury Tracer; (Front Wheel Bearing)
482041B	2006-12; Mercedes-Benz GL320, GL350, GL450, GL550, ML320, ML350, ML450, ML500, ML550, ML63 AMG, R320, R350, R500, R63 AMG; (Front & Rear Wheel Bearing)
530017	2019; Nissan Murano; (Front Left Hub Assembly)
750009	2015-19; Kia Sedona; (Front Hub Assembly)
360029	2017-20; Honda Civic Type R; (Rear Hub Assembly)
530018	2019; Nissan Murano; (Front Right Hub Assembly)
690035	2019-20; Toyota Rav4; (Rear Hub Assembly)
363567	2016-19; Honda HR-V; (Rear Hub Assembly)
114430	2017-18; Ford Fusion / Lincoln MKZ; (Rear Hub Assembly)
693405	2009-13; Pontiac Vibe; Toyota Matrix; (Rear Hub Assembly)
116129	2003-11; Ford Ranger / Mazda B4000; (Front Hub Assembly)
270006	2009-19; BMW 528i, 535d, 535i, 535i GT, 550i, 550i GT, 550i GT xDrive, 640i, 640i Gran Coupe, 650i, 605i Gran Coupe, 740i, 740 Li, 750i, 750Li, 760Li, ActiveHybrid 5, ActiveHybrid 7, Alpine B7, Alpine B7L / Rolls-Royce Cullinan, Dawn, Ghost, Phantom, Wraith; (Front Hub Assembly)
480011B	2002-18; Mercedes-Benz G500, G55 AMG, G550, G63 AMG, G65 AMG; (Front Inner Wheel Bearing)
480012B	2001-20; Mercedes-Benz C230, C240, C250, C280, C300, C32 AMG, C320, C350, C55 AMG, CLK320, CLK350, CLK500, CLK55 AMG, CLK550, CLK63 AMG, E350, E400, E550, SLC300, SLC43 AMG, SLK250, SLK280, SLK300, SLK350, SLK55 AMG; (Front Wheel Bearing)
360032	2006-11; Honda Civic; (Front Wheel Hub)
360013	2005-11; Honda Odyssey; (Front Wheel Hub)

East Coast 2725 New Cut Road, Spartanburg, SC 29303  
 West Coast 950 N 119th Ave, Suite 100, Avondale, AZ 85323

864.578.6900  
 480.418.3405



[www.gspnorthamerica.com](http://www.gspnorthamerica.com)



WHEEL HUBS

# NEW PRODUCT ANNOUNCEMENT

## New Part Numbers

Bulletin No. WH072022

GSP #	DESCRIPTION
360025	1992-03; Lexus RX300; Toyota Camry, Solara; (Front Wheel Hub)
370003	2000-11; Hyundai Accent / Kia Rio, Rio5; (Front Wheel Hub)
370004	2001-06; Hyundai Elantra; (Front Wheel Hub)
370005	2003-17; Hyundai Tucson, Sonata; Kia Optima, Rondo, Sportage; (Front Wheel Hub)
370006	2007-13; Hyundai Elantra; Kia Forte, Forte koup; (Front Wheel Hub)
370007	2001-09; Hyundai Tucson, Santa Fe, Kia Sportage; (Front Wheel Hub)
370009	2002-05; Hyundai Sonata, Kia Magentis, Optima; (Front Wheel Hub)
370013	1999-02; Hyundai Sonata; Kia optima; (Front Wheel Hub)
390001	2000-13; Infiniti I30, I35; Nissan Altima, Maxima, X-Trail; (Front Wheel Hub)
510001	1993-06; Mitsubishi Lancer, Mirage; (Front Wheel Hub)
510002	2007-19; Mitsubishi Lancer, Outlander, Outlander Sport; (Front Wheel Hub)
510004	2003-07; Mitsubishi Lancer; (Front Wheel Hub)
530001	2002-06; Nissan Altima; (Front Wheel Hub)
530002	2000-06; Nissan Sentra; (Front Wheel Hub)
530010	1993-02; Nissan Quest; (Front Wheel Hub)
660004	1990-02; Subaru Forester, Impreza, Legacy; (Front Wheel Hub)
690004	2001-17; Toyota Camry, Highlander, Solara; (Front Wheel Hub)
690005	2003-22; Lexus GX460, GX470; Toyota 4Runner, FJ Cruiser, Tacoma; (Front Wheel Hub)
690011	1993-02; Toyota Corolla; (Front Wheel Hub)
690014	2006-19; Toyota Prius C, Yaris; Scion iQ; (Front Wheel Hub)
720003	1992-99; Volkswagen Golf, jetta, Passat, Corrado; (Front Wheel Hub)
750003	2003-05; Kia Rio; (Front Wheel Hub)
750004	2001-02; Kia Rio; (Front Wheel Hub)
230004	2007-21; Audi A6, A6 Quattro; (Front/Rear Wheel Hub)
530103	1998-02; Infiniti G20; Nissan Altima; (Front Wheel Hub)
530109	2002-06; Nissan Sentra; (Front Wheel Hub)
530129	2003-08; Nissan 350Z; (Rear Wheel Hub)
530132	2003-08 Infiniti FX35 (Rear Wheel Hub)
120008	2020; Ram ProMaster 1500; (Front Both Wheel Hub)



WHEEL HUBS

# NEW PRODUCT ANNOUNCEMENT

## New Part Numbers

Bulletin No. WH072022

GSP #	DESCRIPTION
271080B	1993-10; BMW 325i, 325Xi, 330Ci, 330i, 330xi, 740i, 740Li, 840Ci, 850Ci, 850CSi, 850i, M3, X3, X5, Z3, Z4, Z8 / Mercedes-Benz B Electric Drive, B250e, CLA250, CLA45 AMG, GLA250, GLA45 AMG; (Front & Rear Wheel Bearing)
702140B	2010-20; Porsche 911, Panamera; (Front & Rear Wheel Bearing)
690029B	1990-19; Ford E-150, E-250, E-250 Econoline, E-250 Econoline Club Wagon, E-350 Econoline, E-350 Econoline Club Wagon, E-350 Super Duty, E-450 Econoline Super Duty, E-450 Super Duty, Econoline Super Duty, Excursion, F Super Duty, F-250, F-250 HD, F-250 Super Duty, F-350, F-350 Super Duty, F53, F59; (Front Outer Wheel Bearing)
483012B	2010-18; Mercedes-Benz Sprinter 3500 (Rear Inner Bearing)
941102B	2005-15; Mazda 3, 5, 6; (Front Wheel Bearing) Replaces NA 11010
121123B	2015-20; Ram Promaster City; (Front Wheel Bearing)
361088B	2017-20; Acura MDX / Honda Ridgeline; (Front Wheel Bearing)
110014B	2018-20; Ford EcoSport; (Front Wheel Bearing)
110015B	2012-20; Ford F-250 Super Duty, F-350 Super Duty; (Front Outer Wheel Bearing)
127016B	2014-19; Ram ProMaster 1500, ProMaster 2500, ProMaster 3500; (Front Wheel Bearing)
122018B	2014-19; Ram ProMaster 1500, ProMaster 2500, ProMaster 3500; (Rear Wheel Bearing)
690040	2016-20; Toyota Yaris, Yaris A / Scion iA; (Front Hub Assembly)
116176	2018-20; Ford Expedition / Lincoln Navigator; (Front Hub Assembly)
824423	2018-20; Jeep Wrangler; (Front Hub Assembly)
110021	2020; Ford F-150; (Front Hub Assembly)
112019	2018-20; Ford Expedition / Lincoln Navigator; (Rear Hub Assembly)
110022	2020; Ford Explorer, Police Interceptor Utility / Lincoln Aviator; (Front Hub Assembly)
120009	2019-20; Ram 2500, 3500; (Front Hub Assembly)
116182	2017-19; Ford F-350 Super Duty; (Front Hub Assembly)
116183	2017-20; Ford F-250 Super Duty, F-350 Super Duty; (Front Hub Assembly)



WHEEL HUBS

# NEW PRODUCT ANNOUNCEMENT

## New Part Numbers

Bulletin No. WH072022

GSP #	DESCRIPTION
693628	2016-20; Acura MDX / Honda Passport, Pilot; (Rear Hub Assembly)
360031	2017-20; Honda Clarity; (Rear Hub Assembly)
690041	2019-20; Toyota Highlander, RAV4; (Front Hub Assembly)
123445	2009-10; Ford Edge / Lincoln MKX; (Rear Hub Assembly)
116194	2015-17; Ford F-150; (Front Hub Assembly)
513563	2012-19; Mitsubishi Eclipse Cross, Outlander, Outlander Sport, RVR; (Rear Hub Assembly)
103593	2017-20; Buick Enclave / Cadillac TX5 / Chevrolet Traverse; (Front & Rear Hub Assembly)
103508	2013-17; Buick Verano / Chevrolet Cruze, Volt; (Rear Hub Assembly)
106167	2015-20; Chevrolet Colorado, Canyon; (Front Wheel Hub Assembly)
693546	2013-19; Lexus GS200t, GS300, GS350, GS450h, IS200t, IS250, IS300, IS350, RC200t, RC300, RC350; (Rear Hub Assembly)
513564	2013-19; Mitsubishi Eclipse Cross, Outlander, Outlander PHEV, Outlander Sport, RVR; (Rear Hub Assembly)
832017	1999-04; Land Rover Discovery; (Rear Hub Assembly)
723524	2010-17; Volvo XC60; (Rear Hub Assembly)
233598	2009-20; Audi A4, A5, A6; (Rear Hub Assembly)

QUALITY DRIVEN PERFORMANCE

East Coast 2725 New Cut Road, Spartanburg, SC 29303  
West Coast 950 N 119th Ave, Suite 100, Avondale, AZ 85323

864.578.6900  
480.418.3405



[www.gspnorthamerica.com](http://www.gspnorthamerica.com)