



CV AXLES

NEW PRODUCT ANNOUNCEMENT

78 New Part Numbers

Bulletin No. CVA062022

GSP North America is pleased to announce the release of 78 New CV Axle Part Numbers.

IN STOCK & READY TO SHIP

GSP #	Description
NCV11215	2020-21; Ford Explorer, Police Interceptor Utility / Lincoln Aviator; (Rear Left)
NCV83038	2016-19; Land Rover Defender 110, Discovery, Range Rover, Range Rover Sport; (Rear Left)
NCV37103	2013-19; Hyundai Santa Fe, Santa Fe XL; (Rear Left)
NCV27068	2014-21; BMW i3, i3s; (Rear Left)
NCV27069	2014-21; BMW i3, i3s; (Rear Right)
NCV21064	2015-2020; Acura TLX; (Front Left)
NCV75107	2012-13 Kia Optima (Front Left)
NCV69197	2017-20; Toyota Sienna FWD; (Front Right)
NCV69198	2017-19; Toyota Sienna; (Front Left)
NCV11208	2012-17; Land Rover Discovery Sport, Range Rover Evoque; (Front Left)
NCV23045	2012-13; Audi TTRS Quattro; (Front Left)
NCV37104	2009; Kia Borrego; (Front Left)
NCV37105	2009; Kia Borrego; (Front Right)
NCV47078	2016-19; Mazda CX-3; (Front Left)
NCV51020	2011; Mitsubishi Outlander Sport; (Front Right)
NCV23046	2017-21; Audi RS3, TT RS Quattro; (Front Right)
NCV23047	2015-16; Audi A3; (Front Left)
NCV23048	2008-19; Audi TT Quattro, TTS Quattro; (Front Right)
NCV27066	2012-16; BMW ActiveHybrid 5; (Rear Left)
NCV27067	2012-16; BMW ActiveHybrid 5; (Rear Right)
NCV48059	2018-21; Mercedes-Benz GLC350e; (Front Right)
NCV48062	2015-21; Mercedes-Benz C400, C43 AMG; (Rear Both)
NCV48065	2010-11; Mercedes-Benz E550; (Rear Both)
NCV49036	2016-21; Mini Cooper Clubman, Cooper Countryman; (Front Left)
NCV49037	2016-21; Mini Cooper Clubman, Cooper Countryman; (Front Right)
NCV66051	2014; Subaru Forester; (Front Both)
NCV66052	2014-16; Subaru Impreza; 2.0L; (Front Both)
NCV70035	2015-19; Porsche Macan; (Rear Both)
NCV70036	2011-18; Porsche Cayenne; (Rear Both)
NCV69199	2012-14; Toyota Rav4 EV; (Front Both)
NCV10149	2017-19; GMC Acadia; (Front Left)
NCV47080	2013-16; Mazda CX-5; (Front Left)
NCV23018	2008-18; Audi A3 Quattro, Q3 Quattro, TTRS Quattro / Volkswagen CC, Golf R, R32, Tiguan, Tiguan Limited; (Rear Left)
NCV72029	2008-18; Audi A3 Quattro, Q3 Quattro, TTRS Quattro / Volkswagen CC, Golf R, R32, Tiguan, Tiguan Limited; (Rear Right)

QUALITY DRIVEN PERFORMANCE

East Coast 2725 New Cut Road, Spartanburg, SC 29303
West Coast 950 N 119th Ave, Suite 100, Avondale, AZ 85323

864.578.6900
480.418.3405



www.gspnorthamerica.com

GSP #	Description
NCV69196	2016-21; Lexus RX350, RX350L; (Front Right)
NCV11207	2017-18; Ford Fusion Hybrid; (Front Right)
NCV11210	2013-19; Ford Escape; FWD (Front Right)
NCV69106XD	2013-18; Toyota RAV4; (Front Right)(Extreme Weather)
NCV75108	2012-13; Kia Optima; (Front Right)
NCV47079	2013-16; Mazda CX-5; (Front Right)
NCV11209	2012-17; Land Rover Discovery Sport, Range Rover Evoque; (Front Right)
NCV47077	2016-19; Mazda CX-3 FWD; (Front Right)
NEX23000	1993-02; Volkswagen Cabrio, Golf, Jetta, Passat; (Rear Left)
NEX23001	1993-02; Volkswagen Cabrio, Golf, Jetta, Passat; (Rear Right)
NEX23002	1993-02; Volkswagen Cabrio, Golf, Jetta; (Rear Both)
NEX23003	1998-10; Audi TT, TT Quattro / Volkswagen Beetle, Golf, Jetta; (Rear Both)
NCV11217	2016-18; Ford Focus; (Front Right)
NCV37108	2017-19; Hyundai Ioniq; (Front Right)
NCV11084	2019-21; Ford Ranger 2.3L w/Turbo; (Front Right)
NCV11085	2019-21; Ford Ranger 2.3L w/Turbo; (Front Left)
NCV37101	2019-21; Hyundai Elantra, Veloster; (Front Left)
NCV37102	2019-21; Hyundai Elantra, Veloster; (Front Right)
NCV11508XD	2007-15; Ford Edge / Lincoln MKX; (Front Left) (Extreme Temperatures)
NCV47592XD	2007-13; Ford Edge / Lincoln MKX / Mazda CX-7; (Front Right) (Extreme Temperatures)
NCV11509XD	2007-15; Ford Edge / Lincoln MKX; (Front Right) (Extreme Temperatures)
NCV11211	2016-18; Ford Focus; (Front Right)
NCV11212	2016-18; Ford Focus; (Front Left)
NCV11213	2019-21; Ford Edge / Lincoln Nautilus; (Rear Both)
NCV11214	2019-21; Ford Edge / Lincoln Nautilus; (Rear Left)
NCV11216	2014-20; Ford Transit Connect; (Front Left)
NCV11218	2020-21; Ford Explorer, Police Interceptor Utility / Lincoln Aviator; (Front Left)
NCV11219	2020-21; Ford Explorer, Police Interceptor Utility / Lincoln Aviator; (Front Right)
NCV36195	2016-21; Honda HR-V; (Front Left)
NCV37106	2017-20; Hyundai Elantra / Elantra GT; Front Left)
NCV37107	2017-20; Hyundai Elantra / Elantra GT; Front Right)
NCV48054	2017-19; Mercedes-Benz E300, GLC300; (Rear Both)
NCV48055	2017-19; Mercedes-Benz E300, GLC300; (Rear Both)
NCV48057	2016-21; Mercedes-Benz GLC300, GLC43 AMG; (Front Right)
NCV48058	2016-21; Mercedes-Benz GLC300, GLC43 AMG; (Front Left)
NCV48060	2015-21; Mercedes-Benz C300, C400; (Rear Left)
NCV48061	1998-03; Mercedes-Benz E320 Wagon; (Rear Both)
NCV48063	2014-21; Mercedes-Benz CLA250, CLA45 AMG, GLA250, GLA45 AMG; (Front Left)
NCV48064	2015-21; Mercedes-Benz CLA250, CLA45 AMG, GLA250, GLA45 AMG; (Front Right)
NCV69195	2017-19; Toyota Highlander; (Front Left)
NCV73077	2016-21; Volvo V90 Cross Country, XC60, XC90, (Front Right)
NCV73078	2016-21; Volvo V90 Cross Country, XC60, XC90, (Front Left)
NCV82054	2017-18; Jeep Cherokee; (Front Left)
NCV11220	2020-21; Ford Explorer, Police Interceptor Utility / Lincoln Aviator; (Rear Right)

QUALITY DRIVEN PERFORMANCE