

TECHNICAL BULLETIN—July 2025 

**Program Update Version: v1.5.4**

## SUMMARY:

A software update (v1.5.4) is now available for all Star Wars Pusher 2P units. This update includes key component replacements to improve system reliability and resolve gameplay issues.

## UPDATE DETAILS:

### 1.Solenoid Protection Enhancement

Protects against solenoid failure or overheating during extended use.

### 2. Party Time Button Bug Fix

Resolves an issue in which the shooting button may malfunction during “Party Time” mode activated during the Big Wheel bonus game.

## REQUIRED PARTS (2 TOTAL):

Part Number	Part Name/Description	Return Req.	Price
ASTP0PCB001	MAIN TOP PCB ASS'Y v1.5.4	✓ YES	Full credit with return
AZZZ0PCB203	SOL FET 2CH PCB ASS'Y v2	✓ YES	Full credit with return

*Both parts must be returned post-installation for credit.*

## PROCESS:

- Update parts will be shipped to distributors.
- Distributors are advised to submit a warranty PO per machine.
- Direct shipments are permitted if approved.

## SHIPPING & TIMING:

- Replacement parts are now in stock.
- All new Star Wars Pusher shipments will include the update.

**QUESTIONS?** [service@andamirousa.com](mailto:service@andamirousa.com)

