

Plotting Widget



Use the Plotting widget to plot flight data & calculated parameters. Analyze trends for remote diagnostics and monitoring for up to 4 engine(s) at the same time.

Follow this step by step process:

1. Go to myCFMportal.com
2. Access by adding the plotting widget using the +Add Widget button
3. Use the settings menu to set up parameters including flight phase, graph type and/or secondary axis.
4. To save time when adding more than one Plotting widget, Save and Load Preset(s) to configure standard plot settings.
5. Hover over individual data points to see date/time and values. Hollow circles represent raw data, filled in circles represent smoothed (averaged) data.
6. Look for step shifts or slow trends deviating from initialized values.
7. Modify scales using the down arrow button and add limit lines using the settings menu.

