

BLASTING NOTICE

BLASTING WILL OCCUR

Monday to Friday at 3:30PM

BLASTING SIGNAL

THREE SHORT AIR HORN BURSTS
20 SECONDS PRIOR TO THE BLAST

ALL CLEAR

ONE PROLONGED AIR HORN BURST

Noise and vibrations may be experienced
for 3-5 seconds during the blast.