

Tech Team report of 3/30/2025

There is an ongoing issue with the unpredictable loss of the video signal, the screens will usually black out temporarily.

At this time, two possible causes are suspected, a loose connection in the video side of the system or the more challenging problem of a failing component. Unable to re-create the problem, thus it is difficult to isolate the problem cable or component.

Respectfully submitted,  
Ray Jauregui