Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
3	Live oak	*Quercus virginiana*	21"	n/a	25'	20%	50x38	Co-canopy, canopy is heavy with vine, poor structure, co-dominant branch union with included bark

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
4	Live oak	*Quercus virginiana*	14"	n/a	25'	30%	40x30	Sub-canopy, canopy is heavy with vine, co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
5	Live oak	*Quercus virginiana*	18"	n/a	25'	40%	45x45	Co-canopy, canopy is heavy with vine, co-dominant branch union with included bark, root obstruction from retaining wall



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
6	Live oak	*Quercus virginiana*	17"	n/a	25'	45%	40x40	Co-dominant branch union, root obstruction from retaining wall

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
43	Silver buttonwood	*Conocarpus erectus var. sericeus*	2"	n/a	7'	60%	4x4	Pruned and maintained as topiary

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
44	Silver buttonwood	*Conocarpus erectus var. sericeus*	2"	n/a	7'	60%	4x4	Pruned and maintained as topiary

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
51	Ficus nitida	*Ficus microcarpa*	19"	n/a	35'	40%	30x30	Co-canopy, roots obstruction on two sides of the trunk, co- dominant branch union, overlifted and overextended first order branches

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
52	Ficus nitida	*Ficus microcarpa*	26"	n/a	35'	40%	50x40	Co-canopy, roots obstruction on two sides of the trunk, co- dominant branch union, overlifted and overextended first order branches

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
53	Ficus nitida	*Ficus microcarpa*	38"	n/a	30'	20%	28x20	Co-canopy, roots obstruction on two sides of the trunk, co- dominant branch union, overlifted and overextended first order branches, decay in first order branches

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
54	Green buttonwood	*Conocarpus erectus*	15"	n/a	35'	60%	28x28	Multi co- dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
55	Yellow tabebuia	*Tabebuia chrysotricha*	13"	n/a	8'	40%	12x8	Multi stemmed, three main trunks

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
56	Live oak	*Quercus virginiana*	17"	n/a	25'	30%	30x30	Root obstruction on one side of the trunk, previously removed lower first order branch which has resulted in an open cavity with visible decay, co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
57	Live oak	*Quercus virginiana*	22"	n/a	35'	60%	50x50	Co-canopy, co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
58	Pink tabebuia	*Tabebuia rosea*	6"	n/a	20'	60%	16x16	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
59	Yellow tabebuia	*Tabebuia chrysotricha*	7"	n/a	20'	30%	15x12	Sub-canopy, poor structure

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
60	Sabal palm	*Sabal palmetto*	n/a	15'	n/a	60%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
61	Sabal palm	*Sabal palmetto*	n/a	15'	n/a	60%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
62	Live oak	*Quercus virginiana*	18"	n/a	35'	40%	65x30	Sub-canopy, co-dominant branch union, poor structure



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
65	Yellow tabebuia	*Tabebuia chrysotricha*	8"	n/a	25'	30%	16x16	Sub-canopy, co- dominant branch union, very poor structure

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
66	Ficus nitida	*Ficus microcarpa*	48"	n/a	35'	20%	50x50	Root obstruction on one side of the trunk, previously failed first order branches resulting in major decay, dead branches over the sidewalk, overlifted first order branches

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
67	Ficus nitida	*Ficus microcarpa*	26"	n/a	35'	40%	50x40	Co-canopy, root obstruction on two sides of the trunk, co- dominant branch union, overlifted and overextended first order branches

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
68	Ficus nitida	*Ficus microcarpa*	22"	n/a	35'	40%	50x40	Co-canopy, root obstruction on two sides of the trunk, co- dominant branch union, overlifted and overextended first order branches
69	Ficus nitida	*Ficus microcarpa*	23"	n/a	35'	40%	45x38	Co-canopy, co-dominant branch union, heavy with vine

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
70	Ficus nitida	*Ficus microcarpa*	24"	n/a	35'	40%	50x40	Co-canopy, root obstruction on two sides of the trunk, co- dominant branch union, overlifted and overextended first order branches
71	Ficus nitida	*Ficus microcarpa*	29"	n/a	35'	40%	60x50	Co-canopy, multi co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
72	Ficus nitida	*Ficus microcarpa*	24"	n/a	30'	40%	45x35	Co-canopy, root obstruction on two sides of the trunk, co- dominant branch union, overlifted and overextended first order branches

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
73	Ficus nitida	*Ficus microcarpa*	28"	n/a	30'	30%	50x35	Co-canopy, multi co-dominant branch union, very poor structure
74	Ficus nitida	*Ficus microcarpa*	24"	n/a	30'	30%	40x30	Sub-canopy, co-dominant branch union, root obstruction on two sides of the trunk

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
75	Ficus nitida	*Ficus microcarpa*	29"	n/a	30'	45%	50x42	Co-canopy, multi co-dominant branch union, poor structure



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
76	Live oak	*Quercus virginiana*	13"	n/a	25'	30%	40x25	Co-canopy, poor structure



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
77	Live oak	*Quercus virginiana*	23"	n/a	25'	40%	55x50	Co-canopy, co-dominant branch union, previous second order branch failure

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
78	Live oak	*Quercus virginiana*	7"	n/a	15'	25%	18x13	Sub-canopy



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
80	Live oak	*Quercus virginiana*	23"	n/a	30'	40%	60x30	Co-canopy, asymmetrical canopy, co-dominant branch union, poor structure

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
81	Live oak	*Quercus virginiana*	13"	n/a	25'	25%	25x18	Root obstruction on one side of the trunk, fruiting body of a mushroom indicating internal decay, asymmetrical canopy, poor structure

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
82	Dahoon holly	*Ilex cassine*	6"	n/a	20'	50%	28x22	Root obstruction on two sides



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
83	Live oak	*Quercus virginiana*	21"	n/a	30'	40%	60x50	Co-canopy, co-dominant branch union, previously failed second order branches

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
84	Sabal palm	*Sabal palmetto*	n/a	15'	n/a	70%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
85	Sabal palm	*Sabal palmetto*	n/a	20'	n/a	70%	12x12	



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
86	Sabal palm	*Sabal palmetto*	n/a	15'	n/a	70%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
87	Live oak	*Quercus virginiana*	14"	n/a	30'	50%	36x30	Root obstruction on one side of the trunk,
88	Live oak	*Quercus virginiana*	13"	n/a	25'	40%	20x16	Asymmetrical canopy, poor structure
90	Areca palm	*dypsis lutescens*	n/a	8'		70%	18x18	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
91	Pink tabebuia	*Tabebuia rosea*	6"	n/a	18'	30%	16x16	Co-dominant branch union with included bark, major tip decline, root obstruction on two sides of the trunk

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
92	Jacaranda	*Jacaranda mimosifolia*	10"	n/a	25'	40%	28x28	Co-dominant branch union with included bark, root obstruction on four sides of the trunk

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
93	Live oak	*Quercus virginiana*	23"	n/a	40'	30%	55x36	Co-canopy, root obstruction on four sides of the trunk, overlifted trunk for visual clearance for the building, co-dominant branch union, trunk torsion has previously occurred and it's evident on the trunk where the tree compartmentalized the area



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
94	Live oak	*Quercus virginiana*	24"	n/a	40'	30%	62x52	Co-canopy, root obstruction on four sides of the trunk, overlifted trunk for visual clearance for the building, co-dominant branch union, poor structure

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
95	Gumbo limbo	*Bursera simaruba*	12"	n/a	27'	40%	35x30	Sub-canopy, root obstruction on two sides, co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
96	Yellow tabebuia	*Tabebuia chrysotricha*	15"	n/a	30'	45%	38x38	Co-canopy, root obstruction on two sides, co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
97	Sabal palm	*Sabal palmetto*	n/a	25'	n/a	70%	12x12	



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
98	Sabal palm	*Sabal palmetto*	n/a	23'	n/a	70%	12x12	



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
99	Sabal palm	*Sabal palmetto*	n/a	23'	n/a	70%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
102	Sylvester Date Palm	*Phoenix sylvestris*	n/a	25'	n/a	60%	22x22	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
103	Dahoon holly	*Ilex cassine*	10"	n/a	25'	60%	18x18	Co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
104	Dahoon holly	*Ilex cassine*	11"	n/a	25'	60%	20x20	Co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
105	Dahoon holly	*Ilex cassine*	7"	n/a	23'	60%	18x18	Co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
106	Sabal palm	*Sabal palmetto*	n/a	17'	n/a	60%	12x12	
107	Sabal palm	*Sabal palmetto*	n/a	17'	n/a	70%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
108	Sabal palm	*Sabal palmetto*	n/a	15'	n/a	60%	12x12	



Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
114	Dahoon holly	*Ilex cassine*	10"	n/a	25'	40%	18x18	Co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
115	Gumbo limbo	*Bursera simaruba*	13"	n/a	25'	40%	30x30	Co-canopy, root obstruction on one side, co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
116	Gumbo limbo	*Bursera simaruba*	17"	n/a	25'	45%	34x34	Co-canopy, root obstruction on three side, multi co-dominant branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
117	Gumbo limbo	*Bursera simaruba*	10"	n/a	20'	45%	24x24	Co-canopy, root obstruction on three side

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
118	Pink tabebuia	*Tabebuia rosea*	5"	n/a	16'	50%	10x10	Nutritional deficiency, canker in the trunk
119 pt1	Pink tabebuia	*Tabebuia rosea*	7"	n/a	22'	70%	22x22	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
119 pt2	Live oak	*Quercus virginiana*	23"	n/a	30'	45%	60x55	Root obstruction on one side of the trunk, co-dominant branch union, overlifted branch union

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
120	Dahoon holly	*Ilex cassine*	6"	n/a	16'	65%	14x14	Root obstruction on two sides of the trunk

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
121	Gumbo limbo	*Bursera simaruba*	16"	n/a	27'	40%	45x45	Root obstruction on two sides of the trunk , multi co- dominant branch union, previously hatracked

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
122	Gumbo limbo	*Bursera simaruba*	7"	n/a	15'	50%	16x16	Root obstruction on two sides of the trunk, sub-canopy

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
123	Live oak	*Quercus virginiana*	12"	n/a	27'	45%	40x40	Root obstruction on one side of the trunk , co-dominant branch union

V

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
124	Sabal palm	*Sabal palmetto*	n/a	12'	n/a	70%	12x12	
125	Sabal palm	*Sabal palmetto*	n/a	9'	n/a	70%	12x12	
126	Sabal palm	*Sabal palmetto*	n/a	17'	n/a	70%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
127	Dahoon holly	*Ilex cassine*	6"	n/a	15'	60%	16x12	Co-dominant branch union, root obstruction on one side

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
128	Green buttonwood	*Conocarpus erectus*	14"	n/a	20'	55%	30x30	Co-dominant branch union, root obstruction on one side

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
129	Weeping fig ficus	*Ficus benjamina*	7"	n/a	22'	50%	30x30	Co-dominant branch union, root obstruction on one side
130	Dahoon holly	*Ilex cassine*	7"	n/a	12'	60%	18x16	Co-dominant branch union, root obstruction on one side

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
131	Live oak	*Quercus virginiana*	27"	n/a	30'	35%	60x60	Root obstruction on two sides of the trunk, co-dominant branch union, many fruiting bodies on the trunk indicating internal decay

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
132	Dahoon holly	*Ilex cassine*	5"	n/a	17'	55%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
133	Sabal palm	*Sabal palmetto*	n/a	13'	n/a	70%	12x12	
134	Sabal palm	*Sabal palmetto*	n/a	13'	n/a	70%	12x12	
135	Sabal palm	*Sabal palmetto*	n/a	13'	n/a	70%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
136	Dahoon holly	*Ilex cassine*	8"	n/a	15'	45%	16x16	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
140	Bottle brush	*Melaleuca viminalis*	7"	n/a	8'	10%	3x3	Previously cut back to a 6' stump, root obstruction on one side of the trunk

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
141	Sabal palm	*Sabal palmetto*	n/a	20'	n/a	70%	12x12	
142	Sabal palm	*Sabal palmetto*	n/a	19'	n/a	70%	12x12	
143	Sabal palm	*Sabal palmetto*	n/a	16'	n/a	70%	12x12	

Tree ID#	Common name	Botanical name	DBH (Inch)	Height CT (FT)	Height OA (FT)	Condition	Canopy Spread (FT)	Notes
144	Live oak	*Quercus virginiana*	8"	n/a	16'	45%	22x22	Root obstruction on two sides of the trunk, co-dominant branch union

Please feel free to contact me should you have any questions.

In Support

_____*Trea Jones*_____

Trea Jones/Sutton Consulting Arborist
ISA Certified Arborist #FL-9929A
TRAQ, Tree Risk Assessment Qualification
PPQ, Pruning Prescription Qualification

Sutton Consulting Arborist is staffed by professional Arborists, Horticulturists, and Landscape Inspectors. We utilize associates with expertise in their fields to provide the most accurate, efficient and useful information available to clients. We stand behind our work and can additionally answer any questions or fulfill needs for additional information or services.