



**Network VP® Controller**

## Board Exchange Details

- Core charge will be invoiced with each board shipped.
- Pre-paid UPS return label will be included with shipment of replacement board to ship failed board back.
- Core charge will be refunded upon receipt of failed board.
- **If failed board is not received within 60 days, core charge will not be refunded.**

## Shipping Details

After receipt of replacement board, package failed board and ship back to us using provided UPS return label to:

**Turf Equipment and Supply Co, Inc.**  
8015 Dorsey Run Road  
Attn: BEP CORE RETURN  
Jessup, MD 20794

## Control and Distribution Boards



### **R102-3497-4.0** Timing Mechanism

Unit: \$249.36  
Core: \$173.31



### **R102-2782** Distribution Board

Unit: \$174.53  
Core: \$121.30 \*May ship as LEAD-FREE part number R102-8576



### **R102-9124** LTC+ to VP Upgrade Distribution Board

Unit: \$174.53  
Core: \$121.30



### **R89-9894** 24-Volt Bus Bar

Unit: \$74.76  
Core: \$51.96 \*May ship as LEAD-FREE part number R102-8392



### **R89-9896** Grounding Bus Bar

Unit: \$74.76  
Core: \$51.96 \*May ship as LEAD-FREE part number R102-8393

## Surge Boards



### **R89-8589** Pump/Common Surge


Unit: \$149.59  
Core: \$103.97



### **R89-9804** 16 Station Surge Board

Unit: \$158.72  
Core: \$110.31

## Output Boards



### **R102-2549** 8 Station Output Module

Unit: \$112.18  
Core: \$77.96 \*May ship as LEAD-FREE part number R102-8242

## Pump/Common Boards



### **R102-3015** Pump/Common Board

Unit: \$124.65  
Core: \$86.63 \*May ship as LEAD-FREE part number R102-8577

## Modems/Radio Boards



### \* **R102-0104** Standard Modem

Unit: \$224.42  
Core: \$155.97 \*May ship as LEAD-FREE part number R102-8568



### \* **R102-0106** Universal Modem (Radio)

Unit: \$224.42  
Core: \$155.97 \*May ship as LEAD-FREE part number R102-8570



### **R102-3125** Radio Power Supply

Unit: \$124.65  
Core: \$86.63 \*May ship as LEAD-FREE part number R102-8277



### **R363-4638** Maxon Radio Transceiver

Unit: \$374.08  
Core: \$259.98 \*Customer frequency needed before this can be shipped.

\* Recommended modems for this controller



**E-OSMAC® Controller**

## Board Exchange Details

- Core charge will be invoiced with each board shipped.
- Pre-paid UPS return label will be included with shipment of replacement board to ship failed board back.
- Core charge will be refunded upon receipt of failed board.
- **If failed board is not received within 60 days, core charge will not be refunded.**

## Shipping Details

After receipt of replacement board, package failed board and ship back to us using provided UPS return label to:

**Turf Equipment and Supply Co, Inc.**  
8015 Dorsey Run Road  
Attn: BEP CORE RETURN  
Jessup, MD 20794

## Control and Distribution Boards



### **R102-0187** Narrowband Receiver Card

Unit: \$349.13 \*Customer frequency needed before this can be shipped.  
Core: \$242.65



### **R89-9449-BS** Wideband Receiver Card

Unit: \$223.35 \*Must be used with Potsag chip  
Core: \$155.23 P/N 102-1758



### **R102-0318** Distribution Board

Unit: \$162.06 \*May ship as LEAD-FREE part  
Core: \$112.63 number R102-8084



### **R89-9894** 24-Volt Bus Bar


Unit: \$74.76 \*May ship as LEAD-FREE part  
Core: \$51.96 number R102-8392



### **R89-9896** Grounding Bus Bar

Unit: \$74.76 \*May ship as LEAD-FREE part  
Core: \$51.96 number R102-8393

## Output Board



### **R102-2549** 8 Station Output Module

Unit: \$112.18 \*May ship as LEAD-FREE part  
Core: \$77.96 number R102-8242

## Pump/Common Board



### **R102-0320** Pump/Common Board

Unit: \$112.17  
Core: \$77.96

## Surge Boards



### **R89-8589** Pump/Common Surge

Unit: \$149.59  
Core: \$103.97



### **R89-9804** 16 Station Surge Board

Unit: \$158.72  
Core: \$110.31

## Upgrade your controllers to Osmac G3



### **118-2987** Osmac G3 Upgrade Kit

Unit: \$1,418.48 **Buy 3, Get 1 Free**  
\*\* Ends 10/01/18 \*\*



**RDR OSMAC® Controller**

## Board Exchange Details

- Core charge will be invoiced with each board shipped.
- Pre-paid UPS return label will be included with shipment of replacement board to ship failed board back.
- Core charge will be refunded upon receipt of failed board.
- **If failed board is not received within 60 days, core charge will not be refunded.**

## Shipping Details

After receipt of replacement board, package failed board and ship back to us using provided UPS return label to:

**Turf Equipment and Supply Co, Inc.**  
8015 Dorsey Run Road  
Attn: BEP CORE RETURN  
Jessup, MD 20794

## Control and Distribution Boards



### **RNLN3485** Narrowband Receiver Card

Unit: \$349.13 \*Must be used with Potsag chip  
Core: \$242.65 P/N 102-1758



### **R102-2012** Narrowband Upgrade Card

Unit: \$402.48 \*Customer frequency needed  
Core: \$279.72 before this can be shipped.

## Output Board



### **RNLN3491A** 8 Station Triac Board

Unit: \$236.89  
Core: \$164.64

## Surge Boards



### **R91-1303** 8 Station Surge Board

Unit: \$227.88  
Core: \$158.38



### **R91-1305** Neutral Surge Board

Unit: \$123.58  
Core: \$85.89



## Network LTC® Plus Controller

### Board Exchange Details

- Core charge will be invoiced with each board shipped.
- Pre-paid UPS return label will be included with shipment of replacement board to ship failed board back.
- Core charge will be refunded upon receipt of failed board.
- **If failed board is not received within 60 days, core charge will not be refunded.**

### Shipping Details

After receipt of replacement board, package failed board and ship back to us using provided UPS return label to:


**Turf Equipment and Supply Co, Inc.**  
8015 Dorsey Run Road  
Attn: BEP CORE RETURN  
Jessup, MD 20794

## Control and Distribution Boards



### R102-0238 Timing Mechanism


Unit: \$349.13  
Core: \$242.65



### R102-0612 Distribution Board

Unit: \$149.59 \*May ship as LEAD-FREE part  
Core: \$103.97 number R102-8078

## Surge Boards



### R89-8589 Pump/Common Surge

Unit: \$149.59 \*May ship as LEAD-FREE part  
Core: \$103.97 number R102-8086



### R89-8521 16 Station Surge Board

Unit: \$187.00  
Core: \$129.97

## Output Board



### R102-0681 8 Station Output Module

Unit: \$149.59  
Core: \$103.97

## Upgrade your controllers to LTC Pro or VP



### 118-4838 LTC Pro Upgrade Kit

Unit: \$1,286.74 **Buy 2, Get 1 Free**  
\*\* Ends 10/01/18 \*\*



### 118-0038 VP Upgrade Kit

Unit: \$1,299.14 **Buy 2, Get 1 Free**  
\*\* Ends 10/01/18 \*\*

## Pump/Common Board



### R102-0682 Pump/Common Board

Unit: \$112.18 \*May ship as LEAD-FREE part  
Core: \$77.96 number R102-8082

## Modems/Radio Boards



### R35-8646 Standard Modem

Unit: \$199.48  
Core: \$138.64



### R89-7519 Standard Modem (Old Version)

Unit: \$224.42 \*Board availability limited,  
Core: \$155.97 recommended only if new  
version does not work.



### Standard Modem

### \* R102-0104 (New Version)

Unit: \$224.42 \*May ship as LEAD-FREE part  
Core: \$155.97 number R102-8568



### Universal Modem

### \* R102-0106 (Radio)

Unit: \$224.42 \*May ship as LEAD-FREE part  
Core: \$155.97 number R102-8570



### R363-4638 Maxon Radio Transceiver

Unit: \$374.08 \*Customer frequency needed  
Core: \$259.98 before this can be shipped.

\* Recommended modems for this controller

Follow us on:



www.turf-equipment.com | 800-827-3711





**Network LTC® 2.0 Controller**

## Board Exchange Details

- Core charge will be invoiced with each board shipped.
- Pre-paid UPS return label will be included with shipment of replacement board to ship failed board back.
- Core charge will be refunded upon receipt of failed board.
- **If failed board is not received within 60 days, core charge will not be refunded.**

## Shipping Details

After receipt of replacement board, package failed board and ship back to us using provided UPS return label to:

**Turf Equipment and Supply Co, Inc.**  
8015 Dorsey Run Road  
Attn: BEP CORE RETURN  
Jessup, MD 20794

## Control and Distribution Boards



### **R89-7169** Timing Mechanism


Unit: \$349.13  
Core: \$242.65



### **R89-6977** Back Plane

Unit: \$157.59  
Core: \$109.53

## Surge Board



### **R91-1307** Communication Surge Board

Unit: \$107.71  
Core: \$74.86

## Output Board



### **R89-7170** 4 Station Output Module

Unit: \$81.00  
Core: \$56.30

## Pump/Common Board



### **R89-7171** Pump/Common Board

Unit: \$113.32  
Core: \$78.76

## Modems/Radio Boards



### **R35-8646** Standard Modem

Unit: \$199.48  
Core: \$138.64



### **\* R89-7519** Standard Modem (Old Version)

Unit: \$224.42  
Core: \$155.97

\*Board availability limited, recommended only if new version does not work.



### **R102-0104** Standard Modem (New Version)

Unit: \$224.42  
Core: \$155.97

\*May ship as LEAD-FREE part number R102-8568

\* Recommended modems for this controller



**Network LTC® 1.1 Controller**

## Board Exchange Details

- Core charge will be invoiced with each board shipped.
- Pre-paid UPS return label will be included with shipment of replacement board to ship failed board back.
- Core charge will be refunded upon receipt of failed board.
- **If failed board is not received within 60 days, core charge will not be refunded.**

## Shipping Details

After receipt of replacement board, package failed board and ship back to us using provided UPS return label to:

**Turf Equipment and Supply Co, Inc.**  
8015 Dorsey Run Road  
Attn: BEP CORE RETURN  
Jessup, MD 20794

## Control and Distribution Boards



### **R91-0537** Timing Mechanism with Terminal Block

Unit: \$349.13  
Core: \$242.65

## Modems/Radio Board



### **R91-0777** Standard Modem


Unit: \$317.10  
Core: \$220.38

## Surge Boards



### **R91-1303** 8 Station Surge Board

Unit: \$227.88  
Core: \$158.38



### **R91-1305** Neutral Surge Board

Unit: \$123.58  
Core: \$85.89



### **R91-1307** Communication Surge Board

Unit: \$107.71  
Core: \$74.86



**Network 8000® Controller**

## Board Exchange Details

- Core charge will be invoiced with each board shipped.
- Pre-paid UPS return label will be included with shipment of replacement board to ship failed board back.
- Core charge will be refunded upon receipt of failed board.
- **If failed board is not received within 60 days, core charge will not be refunded.**

## Shipping Details

After receipt of replacement board, package failed board and ship back to us using provided UPS return label to:


**Turf Equipment and Supply Co, Inc.**  
8015 Dorsey Run Road  
Attn: BEP CORE RETURN  
Jessup, MD 20794

## Control and Distribution Boards



### **R91-1280** Timing Mechanism


Unit: \$349.13  
Core: \$242.65



### **R35-6166** Power Supply

Unit: \$211.95  
Core: \$147.30

## Surge Board



### **R35-7899** Surge Board

Unit: \$224.42  
Core: \$155.97

## Output Board



### **R89-8100** 4 Station Triac Board

Unit: \$81.00  
Core: \$56.30

## Pump/Common Boards



### **R35-6326** Pump Module

Unit: \$81.00  
Core: \$56.30



### **R35-8502** Valve Board

Unit: \$118.41  
Core: \$82.30

## Modems/Radio Boards



### **\* R35-8646** Standard Modem

Unit: \$199.48  
Core: \$138.64



### **R89-7519** Standard Modem (Old Version)

Unit: \$224.42  
Core: \$155.97

\*Board availability limited, recommended only if new



### **R102-0104** Standard Modem (New Version)

Unit: \$224.42  
Core: \$155.97

\*May ship as LEAD-FREE part number R102-8568



### **R102-0106** Universal Modem (Radio)

Unit: \$224.42  
Core: \$155.97

\*May ship as LEAD-FREE part number R102-8570

\* Recommended modems for this controller