Jerry Pate Company ON SITE GOLF CART SERVICE

An exclusive service for property owners of

\$55

STANDARD SERVICE INCLUDES:

- Check steering linkage,gearbox/adjust as required
- Check front alignment
- Lube front suspension and all other fittings
- Lube brake shaft bearing and return spring as required
- Check accelerator pedal/linkage adjust as required
- Lube governor and accelerator pivots
- Inspect air filter
- Check fluid levels and top off fluids
- Check torque converter operation
- Lube F & R lever pivot
- Check exhaust for leaks or breaks
- Check condition of muffler and brackets
- Inspect drive belt
- Check starter/generator belt, adjust as required
- Check tires for wear/damage and adjust tire pressure
- Inspect battery cables, Check water level & hold downs
- Check reverse buzzer operation

DELUXE SERVICE INCLUDES:

All services included in Standard Service Package plus...

Oil change with new oil filter

*Credit Card Only



HOT SPRINGS VILLAGE GATEWAY TO THE OUACHITAS Arkansas

www.JerryPate

OT SPRINGS VILL



SERVICE WILL BE PERFORMED AT THE GOLF CART TRAILER PARKING LOT AT MAGELLAN GOLF CLUB. (Across the street from club house parking lot)

All additional repairs will be quoted for approval.