



Answer D is correct

A weak accessory belt tensioner or a worn accessory belt results in squealing, a flickering charging light, and a flapping belt.