

- Train Data
- System Status
- Configuration
- Logs
- Maintenance Info
- System Functions
- Software Update
- Auto Cal

Train Summary Data (Trains Stored: 100)

Axle Alarms
 Integrity Failures
 System Alarms
 DSR Records

Trn#	Date	Time	Cars	Axles	TO1	TO2	Dir	Speed			Bearing Avg		Wheel max		AEI Tags	Temp	Bat	Alarms
								Min	Max	Exit	East	West	East	West				
704	04/15/19	08:21	116	472	472	472	S	33	41	33	14	19	24	42	0	+40F	14.6v	
703	04/15/19	05:35	105	426	426	426	S	28	41	28	13	17	31	39	0	+39F	14.5v	
+702	04/15/19	05:11	49	332	332	332	S	34	41	34	15	20	66	78	0	+39F	14.5v	
701	04/15/19	03:51	40	252	252	252	S	42	45	42	14	17	146	146	0	+41F	14.5v	
700	04/15/19	03:34	48	386	386	386	S	27	32	27	15	20	154	148	0	+41F	14.4v	
699	04/15/19	02:55	37	154	154	154	S	11	15	15	5	8	0	35	0	+42F	14.4v	
698	04/15/19	02:36	78	318	318	318	S	26	30	26	8	12	118	163	0	+42F	14.4v	
697	04/15/19	02:05	104	422	422	422	S	18	21	18	4	6	20	36	0	+42F	14.3v	
696	04/14/19	23:45	89	360	360	360	S	35	42	35	11	16	20	35	0	+46F	14.3v	
695	04/14/19	22:06	49	204	204	204	N	19	20	19	13	16	36	42	0	+51F	14.2v	
694	04/14/19	20:43	62	266	266	266	S	6	12	9	7	9	20	35	0	+56F	14.1v	
693	04/14/19	20:03	137	560	560	560	S	35	47	35	11	16	31	44	0	+57F	14.1v	
692	04/14/19	18:59	32	216	216	216	S	28	36	28	15	17	35	46	0	+62F	14.1v	
691	04/14/19	17:33	49	330	330	330	S	39	44	39	17	19	80	80	0	+70F	14.0v	
690	04/14/19	16:25	58	248	248	248	N	35	38	35	20	21	28	42	0	+73F	14.0v	
689	04/14/19	16:05	152	614	614	614	S	17	26	17	2	5	24	42	0	+74F	14.0v	
688	04/14/19	12:44	47	192	192	192	S	24	26	24	2	4	16	35	0	+68F	14.1v	
687	04/14/19	11:51	92	378	378	378	N	45	47	45	18	20	36	49	0	+67F	14.2v	
686	04/14/19	11:31	85	346	346	346	N	32	37	32	15	15	28	46	0	+67F	14.2v	
685	04/14/19	08:48	139	564	564	564	S	32	44	32	8	12	20	35	0	+63F	14.2v	
684	04/14/19	08:35	49	220	220	220	S	44	45	44	11	14	24	36	0	+63F	14.2v	
683	04/14/19	08:23	48	284	284	284	S	36	44	36	12	15	128	72	0	+63F	14.2v	
682	04/14/19	07:40	151	612	612	612	S	28	39	28	4	7	64	72	0	+65F	14.2v	
681	04/14/19	07:19	74	302	302	302	S	25	28	25	6	9	28	46	0	+65F	14.2v	
680	04/14/19	05:52	62	356	356	356	S	29	39	29	16	19	31	42	0	+67F	14.2v	
679	04/14/19	04:50	128	518	518	518	S	23	37	23	12	15	28	42	0	+67F	14.2v	
678	04/14/19	01:47	115	466	466	466	N	13	32	13	13	15	118	136	0	+59F	14.2v	
677	04/13/19	20:18	140	568	568	568	N	42	45	43	7	10	31	36	0	+62F	14.1v	
676	04/13/19	19:35	28	216	216	216	S	51	53	51	13	18	35	61	0	+62F	14.2v	
675	04/13/19	18:46	43	304	304	304	S	28	34	28	19	24	114	159	0	+63F	14.1v	
674	04/13/19	18:18	56	246	246	246	S	34	36	34	12	16	28	42	0	+64F	14.1v	
673	04/13/19	18:01	138	560	560	560	S	25	37	25	10	15	28	49	0	+64F	14.1v	
672	04/13/19	17:40	70	286	286	286	S	33	37	33	15	19	31	39	0	+64F	14.1v	

Symbol Legend to quickly identify problem trains