



HANOVER HYANNIS - WEEKLY SITE PHOTOS

WEEK OF MARCH 24, 2023



HANOVER COMPANY

SITE OVERVIEW



BUILDING 1 CLUBHOUSE STEEL FIREPROOFED



BUILDING 1 2ND FLOOR PLUMBING ROUGH ONGOING



BUILDING 1 3RD FLOOR PRE-ROCK ONGOING



BUILDING 1 ROOF TRUSS INSTALL ONGOING



BUILDING 1 TYVEK INSTALL ONGOING



HANOVER COMPANY

BUILDING 2 3RD FLOOR TRUSS LAYOUT AND SHEATHING ONGOING



BUILDING 2 1ST FLOOR MOLD-SPRAY COMPLETE



BUILDING 3 SECTION A/B 1ST FLOOR WALL PANELS ONGOING



BUILDING 3 SECTION C READY FOR SOG POUR



GARAGE F ROOFING COMPLETE



GARAGE E ROOFING COMPLETE



MAILROOM FRAMING ONGOING



RETAINING WALL NEARING COMPLETION

