20-581 HANOVER COLONY PLACE

Weekly Site Photos Week Ending 5/19/2023



Sitework

Top Left – Overall Progress from the Roof of Building 3

Top Right – Phase 1 Sidewalks Complete

Bottom — Phase 1 PM-4 Tile Install Commenced







Level 4 Top Left — Management Walks Complete

Level 3 Top Right – Management Walks Complete

Level 2 Bottom Left – Corridor Carpet Installed

Level 1 Bottom Right — Cabinets, Doors & Trim Install Commenced









Clubhouse

Top Left – Clubroom Millwork Install on Going

Top Right – Fitness Room Lights Installed

Bottom – Screening Room Paint







Overall View - Exterior Punch Substantially Complete



Level 4 Top Left — Ready For Management Walks

Level 3 Top Right – Finishes Complete, Ready for Management Walks

Level 2 Bottom Left — Countertops Installed, Backsplash Commenced

Level 1 Bottom Right — Cabinet Install Nearing Completion









Overall View – Exterior Paint Nearing Completion



Interior Progress

Level 4 Top Left – Cabinet Install Nearing Completion

Level 3 Top Right – Cabinet Install Underway

Level 2 Bottom — Gypcrete Complete







Overall View




Top Left – Masonry on Going. Acid Wash in Progress

Top Right – Siding Install on Going
Bottom, Level 2 – MEPs on Going







Overall View



Mail Building

Wallpaper Complete, Countertops in Progress



