

19-565
Hanover
1230 West
Peachtree

Weekly Site Photos
Week Ending
5/19/2023



North-East

Window Glazing in Progress.

Elastomeric Coating in Progress.

Balcony Rails in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



East Tower

Window Glazing in Progress.

Elastomeric Coating in Progress.

Balcony Rails in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



North Podium

Exterior Tile in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



West Tower

Window Glazing in Progress.

Elastomeric Coating in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 06 Amenity Area

Loggia Work in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



North Amenity Deck

*Topping Slabs Poured on Deck.
Feature Wall and Arbor.*

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 1 Leasing Lobby

Drywall Hanging, Tape and Float in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 9
Mock-Up Units

*Mock-Up Unit Executive Walk
Complete.*
Final Punch Items in Progress.



19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Roof Level

Southwest Catwalk Rails Installed.

*Prepping to Place Condenser Racks
South Side.*



19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 29

Window Framing in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 27

Unit Layout in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 19

Unit Electrical Rough in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 12

*Drywall Finishing Nearing
Completion.*

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 9

Cabinet Installation in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023



Level 7

Countertop Installation in Progress.

Plumbing Trim Out Started.



19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending
5/19/2023

HANOVER