

Project Photos



Week Ending 3/24/2023



View of Southeast Elevation



View of Southern Elevation



View of Southwest Elevation



View of East Elevation



View of the East Elevation – Garage Entry



View of North Elevation



Ground View of Courtyard A



Aerial View of Courtyard A



Ground View of Courtyard B



Aerial View of Courtyard B



Ground View of Courtyard C



View of Courtyard C – Fireplace



Aerial View of Courtyard C – East Elevation



Aerial View of Courtyard C – West Elevation



Ground View of Courtyard D



Aerial View of Courtyard D



Phase 1, Level 3 - QAQC Ongoing



Phase 1, Level 5, Unit MEP Pick Up Ongoing



Phase 1, Level 5, Thresholds Installation Ongoing



Phase 1, Level 6 - Unit MEP Trim Pick Up and Appliance Install Ongoing



Phase 1, Level 6 Corridor Touch-ups Ongoing



Phase 2, Level 4 – Unit Bathroom Tile Installation Ongoing



Phase 2, Level 5 - Production TExture



Phase 2, Level 6 – Insulation and RC Production Ongoing



Phase 2, Level 7 - Unit Rough In Pick Up



Phase 1, Level 3 – Amenity Fitness Room



View of Phase 1, Level 1 Amenity



Phase 1, Level 1 – Meeting Room



Phase 2, Level 1 – Dog Wash



East Entrance Paver Driveway



View of Southeast Storefront



Personnel Hoist Demobilization