

21-613 HANOVER NORTH ROLLINS

Weekly Site Photos
Week Ending

9/1/2023



Overhead Site View 9.1



21-613 Hanover North Rollins
Weekly Site Photos
Week Ending
9/1/2023

Ground Improvements

DDC installation Complete.

Farrell Demobilized.



21-613 Hanover North Rollins
Weekly Site Photos
Week Ending
9/1/2023

Garage Concrete

Reinforcing for garage footing ongoing.

Preparing to pour first footings 9.08



21-613 Hanover North Rollins
Weekly Site Photos
Week Ending
9/1/2023

MEP Underground

Garage Plumbing inspections complete, backfill complete.

Excavating Sewage Ejector and SOI tank starting 9.05.



21-613 Hanover North Rollins
Weekly Site Photos
Week Ending
9/1/2023

Fine Grading


DeSilva Gates fine grading residential pad complete. Pad Cert complete.



21-613 Hanover North Rollins
Weekly Site Photos
Week Ending
9/1/2023

Wet Utilities

Sanco mobilized and near complete with Rollins Storm Drain install.



21-613 Hanover North Rollins
Weekly Site Photos
Week Ending
9/1/2023

HANOVER