



HANOVER
COMPANY

HANOVER Turtle Creek
March 24, 2023 Weekly
Photos



Enid

- **Photo Date: 03/24/2023**
- **Description: New storm tie in install ongoing Enid St.**



Tower 1

- **Photo Date: 03/24/2023**
- **Description: Retaining wall forms arrived on site.**



Tower 1

- **Photo Date: 03/24/2023**
- **Description: Tying pier cages on L1 for pier drilling on B1**



Tower 1

- **Photo Date: 03/24/2023**
- **Description: Drilling piers and setting casing on B1 ongoing.**



Tower 1

- **Photo Date: 03/24/2023**
- **Description: Staging mat foundation piers for drilling operation on B1.**




Tower 1

- **Photo Date: 03/24/2023**
- **Description: Staging mat foundation piers for drilling operation on B1.**



Tower 1

- **Photo Date: 03/24/2023**
- **Description: Setting pier cage to mat foundation.**



Tower 1

- Photo Date: 03/24/2023
- Description: Piers completed to date on B1



Tower 1

- **Photo Date: 03/24/2023**
- **Description: Overall site view – Facing Southeast**