



HANOVER PINEHILLS 2 – WEEKLY SITE PHOTOS

WEEK OF MARCH 24TH, 2023



HANOVER COMPANY

PINEHILLS 2 - JOBSITE OVERVIEW



BUILDING 2 EXTERIOR SIDING NEARING COMPLETION



BUILDING 2 EXTERIOR SIDING NEARING COMPLETION



HANOVER COMPANY

BUILDING 2 EXTERIOR SIDING NEARING COMPLETION



BUILDING 2 EXTERIOR SIDING NEARING COMPLETION



HANOVER COMPANY

BUILDING 2 EXTERIOR SIDING NEARING COMPLETION



BUILDING 2 ROOF CONDENSER INSTALLATION ONGOING



MOCKUP UNIT 2408 - CABINETS AND WOOD FLOORING INSTALLED.



MOCKUP UNIT 2408 - WOOD FLOORING INSTALLED.



MOCKUP UNIT 2408. UNIT BLINDS AND FAN INSTALLED.



MOCKUP UNIT 2406. CABINETS, WOOD FLOORING AND MILLWORK PROGRESS.



MOCKUP UNIT 2406 - HVAC FURNACE AND NAVIEN WATER HEATER



BUILDING 2 LEVEL 4 - CORRIDOR DRYWALL AND TAPE



BUILDING 2 LEVEL 3 - CORRIDOR DRYWALL AND TAPE



BUILDING 2 LEVEL 3 - PAINTING COMPLETE



BUILDING 2 LEVEL 2 - DRYWALL ONGOING



BUILDING 1 EXTERIOR AND MAIL BUILDING



BUILDING 1 - EXTERIOR BRICK AND TYVEK



BUILDING 1 - BLOCKS 3 & 4 FRAMING ONGOING



HANOVER COMPANY

**BUILDING 1 - BLOCKS 3 & 4
LEVEL 4 - ROOF TRUSSES**



BUILDING 1 - CLUBHOUSE



BUILDING 1 - CLUBHOUSE



CLUBHOUSE - RESTROOM PLUMBING



BUILDING 1 TPO AND LINESET

