

20-580 HANOVER HYANNIS

Weekly Site Photos
Week Ending
5/19/2023



Site Overview

Standing on berm looking South

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 1

Brick installation nearing completion



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 1

*4th floor HVAC & plumbing rough
nearing completion*

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 1

*3rd floor HVAC & plumbing rough
ongoing*

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 2

Tyvek and window installation ongoing



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 2

Roof sheathing nearing completion

TPO staged on Section A

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 2

*1st and 2nd floor plumbing rough
ongoing*

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 3

4th floor panel install ongoing



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 3

1st floor NLBW framing nearing completion

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Building 3

2nd floor prerock and NLBW layout ongoing



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Sitework

Binder install phase 1 of 2 complete

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



Courtyard

Pool gunite complete

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
5/19/2023



HANOVER