

19-565
Hanover
1230 West
Peachtree

Weekly Site Photos
Week Ending

6/2/2023



North-East

Window Glazing in Progress.

Elastomeric Coating in Progress.

Balcony Rails in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



East Tower

Window Glazing in Progress.

Elastomeric Coating in Progress.

Balcony Rails in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



North Tower

Loggia Framing in Progress.

Window Glazing in Progress.

Elastomeric Coating in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos

Week Ending

6/2/2023



West Tower

Window Glazing in Progress.

Elastomeric Coating in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 1 Leasing Lobby

Drywall Tape and Float in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 9 Mock-Up Units

*Final Construction Punch in
Progress.*

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023




Level 6 Amenity Area

*Soil Installation in Progress in
Planters.*

*Waterproofing Completed in the
Loggia Area.*

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Roof

TPO on the Elevator Machine Room Roof.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 29

Exterior Window Glazing in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 28

Water Distribution in Progress.

Unit Top Track Started.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 21

Unit Mechanical Rough in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 16

Two-Sided Drywall in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 14

Drywall Finishing in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 11

Interior Door Installation in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 10

Cabinet Installation Started.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 7

Tile Backsplash in Progress.

Electrical Trim-out in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



Level 06 Units

Two-Sided Drywall Hanging in Progress.

19-565 Hanover 1230 West Peachtree
Weekly Site Photos
Week Ending

6/2/2023



HANOVER