

20-581
HANOVER
COLONY
PLACE

Weekly Site Photos
Week Ending
6/02/2023



Sitework

Top Left – Courtyard Sidewalk Progress from the Roof of Building 1

Top Right – Tiered Step Walls at the Gable End of Building 1

Bottom – Pool & Sidewalk Progress



20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23

Building 1



Level 4 Top Left – Management Walks Complete

Level 3 Top Right – Management Walks Complete

Level 2 Bottom Left – Ready For Management Walks

Level 1 Bottom Right – Hallway Paint On Going

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



Clubhouse

Top – Carpet Installation On Going

Bottom Right – Clubhouse Fixtures Installed

Bottom Left – Club Granite Installation On Going

**20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23**



Building 1

*Overall View - Exterior Punch
Substantially Complete*

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



Building 2

Level 4 Top Left – Ready For Management Walks

Level 3 Top Right – Ready for Management Walks

Level 2 Bottom Left – Countertops Installed, Backsplash Commenced

Level 1 Bottom Right – Cabinet Install Nearing Completion

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



Building 2

*Overall View – Exterior Paint
Nearing Completion*

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



Building 3

Interior Progress

Level 4 Top Left – Cabinet Install Complete, Flooring On Going

Level 3 Top Right – Cabinet Install Underway

Level 2 Bottom Left – Doors & Trim Delivered

Level 1 Bottom Right – Sheetrock Units

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



Building 3

Overall View

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



Building 4

Top Left – ISO on 4th Floor On Going



Top Right – Level 3 MEP's Complete



Bottom, Level 2 – MEPs on Going



20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23

Building 4

Overall View

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



Mail Building

*Top – Granite Countertop Install
Complete*

*Bottom – Parcel Room Shelving
Install Commenced*

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
6/02/23



HANOVER