

# 20-586 Hanover Clearfork

---

Weekly Site Photos  
Week Ending  
5/19/2023





## Building 1

*Entry View With the Lights On*

20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023





## Building 2

*Planting Continues*

*Exterior Punch Complete*

20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023






## Building 2

*Level 2 2<sup>nd</sup> Walks Underway*

*Level 1 1<sup>st</sup> Walks Underway*



20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023



## Building 4

*Exterior Paint Punch Underway*

*Gutters and Downspouts Started*

*Concrete Walkup Formed*

20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023





## Building 4

*Level 3 Paint Punch Underway*

*Level 2 Drywall Punch Underway*

*Level 2 Corridor Carpet Stocked for Install*



20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023





## Building 5

*Exterior Paint Complete*

*Romeo and Juliet Rails in Progress*

*Sidewalks Underway*

20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023





# Courtyard

*Top Left: Cabana Cladding in Progress*

*Top Right: Cabana Cladding (Prestained before Hanging, Final Coat to Come)*

*Bottom: View of Cabana from behind Turf*



20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023



# Courtyard

*Top: Grout Install Continues*  
*Bottom Left: Courtyard to Clubroom*  
*Entry Tile Install Underway*  
*Bottom Right: Wood Plank Tile and*  
*Trees Installed*



20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023



# Courtyard

*Brick Columns on the AVAdek  
Structure Underway*

*Dog Run Trees, Landscaping  
Continue*



20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023





# Site Aerials

*Aerial Photo of the Jobsite*

20-586 Hanover Clearfork  
Weekly Site Photos  
Week Ending  
5/19/2023





**HANOVER**