

21-601
HANOVER
TURTLE
CREEK

Weekly Site Photos
Week Ending
6/2/2023



ROUNABOUT

Sanitary Sewer Backfill Complete

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



LEVEL B1 UNDERGROUND

*Level B1 Underground Plumbing
Installation In Progress*

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



LEVEL B1 SLAB ON GRADE

Fine Grading In Progress

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



L1 RETAINING WALL

Level 1 Retaining Wall Backfill In Progress

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



L1 RETAINING WALL & CORE

*Level 1 Retaining Wall and Core
Backfill In Progress*

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



L1 RETAINING WALL

*Concrete Poured, Grinding and
Patching in Progress*

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



SHARED FOUNDATION

*Excavation of Shared Foundation
Between Tower 1 and Garage*

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



SITE

*Overall Site Aerial Photo Dated
5/25*

21-601 Hanover Turtle Creek
Weekly Site Photos
Week Ending

6/2/2023



HANOVER