

20-584
HANOVER
PRESTON
HOLLOW

Weekly Site Photos
Week Ending
6/2/2023



LEVEL 6 POUR 1

*Tables installed, decking and MEP
rough-in ongoing.*

20-584 Hanover Preston Hollow
Weekly Site Photos
Week Ending
6/2/2023



LEVEL 5 POUR 2

Concrete placed 6/2.

20-584 Hanover Preston Hollow
Weekly Site Photos
Week Ending
6/2/2023



LEVEL 4 POURS 3 & 4

Pour 3 concrete placed 6/1. PT, reinforcement, and MEP rough-in ongoing for pour 4.

20-584 Hanover Preston Hollow
Weekly Site Photos
Week Ending
6/2/2023



WET UTILITIES

*Installation of meter vaults ongoing
at Southwest corner of site.*

20-584 Hanover Preston Hollow
Weekly Site Photos
Week Ending
6/2/2023



LEVEL B1

Removal of reshoring and installation of overhead plumbing pipe continued.



20-584 Hanover Preston Hollow
Weekly Site Photos
Week Ending
6/2/2023



SITE OVERVIEW

Facing Northwest 6/2.

20-584 Hanover Preston Hollow
Weekly Site Photos
Week Ending
6/2/2023



HANOVER