

20-586 Hanover Clearfork

Weekly Site Photos
Week Ending

6/2/2023



Building 1

Clubhouse Entry

20-586 Hanover Clearfork
Weekly Site Photos
Week Ending

6/2/2023



Building 4

Exterior Paint Punch Complete

*Gutters and Downspouts
Substantially Complete*

Concrete Walkup Poured

Storefront Prepped for Install

20-586 Hanover Clearfork

Weekly Site Photos

Week Ending

6/2/2023



Building 4

Level 3 Paint Punch Substantially Complete

Level 2 Paint Punch Started

Level 1 Drywall Punch Substantially Complete



20-586 Hanover Clearfork
Weekly Site Photos
Week Ending

6/2/2023

Building 5

Exterior Paint Complete

Romeo and Juliet Rails Complete

Sidewalks Underway

20-586 Hanover Clearfork

Weekly Site Photos

Week Ending

6/2/2023



Building 5

Level 2 Entry Hardware Installed

Level 1 Wood Floor Complete

Basement Wood Flooring Stocked to Start



20-586 Hanover Clearfork
Weekly Site Photos
Week Ending

6/2/2023

Mail/Bike Room

Top: Bike Room Floor Epoxyed

Bottom Left: Mail Room

Bottom Right: Mail Room



20-586 Hanover Clearfork
Weekly Site Photos
Week Ending


6/2/2023

Courtyard

Top: Pool

Bottom Left: Furniture Set out at Fireplace Feature

Bottom Right: Wood Plank Tile and Trees




**20-586 Hanover Clearfork
Weekly Site Photos
Week Ending**

6/2/2023

Courtyard

Furniture by the Pool Set Out




20-586 Hanover Clearfork
Weekly Site Photos
Week Ending

6/2/2023

Courtyard

*Dog Run Landscaping Continues
Courtyard Landscaping Continues*




20-586 Hanover Clearfork
Weekly Site Photos
Week Ending
6/2/2023

Courtyard

*Brick Columns on the AVAdek
Structure Underway*

Grills and Firepits Underway



**20-586 Hanover Clearfork
Weekly Site Photos
Week Ending**

6/2/2023

HANOVER