

# 18-536 HANOVER WALNUT CREEK

---

Weekly Site Photos  
Week Ending

6/2/2023



## Level 6 Units

*Drywall Patching Started In Area 1*



18-536 Hanover Walnut Creek  
Weekly Site Photos  
Week Ending

6/2/2023

## Level 5 Units

*Drywall Patching Ongoing In Area 3*

*Paint Touch Up Starting In Area 1*

18-536 Hanover Walnut Creek

Weekly Site Photos

Week Ending

6/2/2023



## Level 4 Units

*Management Acceptance Walks  
Started In Area 1*

18-536 Hanover Walnut Creek  
Weekly Site Photos  
Week Ending

6/2/2023



## Level 3 Corridor

*Ready For Management 1<sup>st</sup> Walk*


18-536 Hanover Walnut Creek  
Weekly Site Photos  
Week Ending

6/2/2023



## Level 3 Units

*All Level 3 Units Accepted By Management*



18-536 Hanover Walnut Creek  
Weekly Site Photos  
Week Ending

6/2/2023

# Gym

*TRX Bands Installed*


18-536 Hanover Walnut Creek  
Weekly Site Photos  
Week Ending

6/2/2023



## Courtyard A

*Management Punch Near Complete*



18-536 Hanover Walnut Creek  
Weekly Site Photos  
Week Ending

6/2/2023

## Courtyard B

*Tables Delivered and Installed*

18-536 Hanover Walnut Creek  
Weekly Site Photos  
Week Ending

6/2/2023



HANOVER