

# 20-580 HANOVER HYANNIS

---

Weekly Site Photos  
Week Ending

6/2/2023



## Site Overview

*Standing on berm looking South*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending  
6/2/2023



## Building 1

*Brick install complete, window trim  
& storefront framing ongoing*



20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 1

*Storefront framing ongoing*



20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 1

*Electrical cable pulls underway*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023



## Building 1

*2<sup>nd</sup> & 3<sup>rd</sup> floor HVAC &  
plumbing rough ongoing*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023



## Building 1

*Clubhouse fire rated ceiling sheetrock  
ongoing*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023



## Building 2

*Tyvek, window & brick installation  
ongoing*



20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 2

*TPO ongoing*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023



## Building 2

*4<sup>th</sup> floor NLBW framing ongoing*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023



## Building 2

*2<sup>nd</sup> floor plumbing rough ongoing*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023



## Building 3

*Roof sheathing ongoing*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending  
6/2/2023



## Building 3

*2<sup>nd</sup> floor NLBW framing ongoing*

20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023



## Sitework

*Binder phase 2 of 2 complete*



20-580 Hanover Hyannis  
Weekly Site Photos  
Week Ending

6/2/2023

HANOVER