

# 19-569 Hanover Winchester

---

Weekly Site Photos  
Week Ending

9/1/2023



## Exterior

*View of East Elevation*

19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023



## Exterior

*View of West Elevation – Zipper Units Fiber Cement Install Complete*

19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023



## Exterior

*View of Northern Elevation*

19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023



## Courtyard C

*Aerial View (Left)*

*Ground Views (Right)*

19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023



## Courtyard D

*Aerial View (Left)*

*Ground Views (Right)*

19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023



## Phase 1

*Level 7 – Appliance Install  
Complete*

19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023



## Phase 2


*Level 5 – Cabinet Install Ongoing (Top Left)*

*Level 6 – Tile Install Ongoing (Top Right)*

*Level 7 – Rough Inspections Complete (Bottom Left)*

**19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending**


**9/1/2023**



## Amenity

*Level 1 – Dog Wash (Top Left)*

*Level 1 – Bike Lounge (Bottom Right)*



19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023

## Amenity

*Lobby Carpet Installed*

19-569 Hanover Winchester  
Weekly Site Photos  
Week Ending

9/1/2023



HANOVER