

18-536 HANOVER WALNUT CREEK

Weekly Site Photos
Week Ending
5/19/2023



North-West Corner

Anti-Graffiti Applied

18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Level 6 Units

Completing Hot Check



18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Level 5 Units

Drywall Patching Ongoing



18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Level 4 Corridor

Preparing For Corridor Punch

18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Level 4 Units

Construction Punch Ongoing



18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Level 3 Corridor

Preparing For Management Walk

18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Level 3 Units

Unit Acceptance In Progress



18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Loggia

Preparing For Management Walk

18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023




Gym

*Echelon Fitness Mirror & Fitness
Equipment Installed*



18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Courtyard A

1st Management Walk Complete

18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



Courtyard B

1st Management Walk Complete

18-536 Hanover Walnut Creek
Weekly Site Photos
Week Ending
5/19/2023



HANOVER