

Weekly Site Photos



Project photos for the week of March 20th to March 24th, 2023.



Jobsite overview



Parking garage progress



Pouring walls for pump room on phase 1



Backfill of retaining wall B.1 on elevation 1026'



Backfill of 1039' field box



Continued installing bracing on retaining wall B.1



Continued waterproofing for phase 1 retaining wall B.1