

20-580 HANOVER HYANNIS

Weekly Site Photos
Week Ending

9/1/2023



Site Overview

View from Wilkens Lane

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
9/1/2023



Building 1

Siding complete, paint ongoing



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending

9/1/2023

Clubhouse

Production drywall commenced

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending

9/1/2023



Building 1

*4th floor corridor gypcrete complete
(top left)*

*Mock up final paint ongoing (top
right)*

*4th floor door/ trim/ cabinet install
ongoing (bottom right)*

**20-580 Hanover Hyannis
Weekly Site Photos
Week Ending**

9/1/2023



Building 1

3rd floor mud & tape ongoing (left)

2nd floor insulation nearing completion (top right)

2nd floor production drywall commenced (bottom right)



**20-580 Hanover Hyannis
Weekly Site Photos
Week Ending**

9/1/2023

Building 1

1st floor electrical nearing completion

20-580 Hanover Hyannis
Weekly Site Photos
Week Ending

9/1/2023



Building 2

Siding & trim install ongoing


20-580 Hanover Hyannis
Weekly Site Photos
Week Ending

9/1/2023



Building 2

4th floor electrical ongoing




20-580 Hanover Hyannis
Weekly Site Photos
Week Ending

9/1/2023

Building 3

4th floor HVAC rough ongoing (left)

Stair D install ongoing (right)



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending

9/1/2023

Courtyard

Mudmats ongoing (left)

Clubhouse courtyard entry mudmat (top right)

Pool mudmat prep (bottom right)



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending
9/1/2023

Sitework

Rain garden planting ongoing (top)

Main entry curbing ongoing (bottom left)

*Clubhouse entry curbing ongoing
(bottom right)*



20-580 Hanover Hyannis
Weekly Site Photos
Week Ending

9/1/2023

HANOVER