

# 21-600 HANOVER PINEHILLS II

---

Weekly Site Photos  
Week Ending

9/1/2023



## Sitework

- *Top - Building 2 Courtyard Overview*
- *Bottom - Elevation facing highway*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

9/1/2023

## Building 2 Exterior

### *Building 2 Courtyard*

- *Exterior Storefront Door Install  
Ongoing*

21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

9/1/2023



## Building 2 Exterior

### *Building 1 Courtyard*

- Retaining wall

21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

9/1/2023




## Building 2 Interior

*Top left – level 4 2<sup>nd</sup> management walks on going*

*Top right – level 3 1<sup>st</sup> management walks complete*

*Bottom left – level 2 1<sup>st</sup> management walks in progress*

*Bottom right – level 1 construction punch nearing completion*



21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

9/1/2023

## Building 1 Exterior

*Front exterior of building 1*

21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

9/1/2023





## Building 1A Interior

*Top left – level 4 MEP trim nearing completion, construction punch in progress*

*Top right – level 3 MEP trim ongoing*

*Bottom left – level 2 finishes ongoing*

*Bottom right – level 1 finishes ongoing*



**21-600 Hanover Pinehills II**

**Weekly Site Photos**

**Week Ending**

**9/1/2023**

## Building 1 Clubhouse

*Overview of clubhouse*




21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

9/1/2023

## Building 1 Clubhouse

*Wall tile at Restrooms*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending  
9/1/2023

## Building 1B - Interior

*Top left – Level 4 Prime Paint ongoing*

*Top right – Level 3 insulation nearing completion, drywall loaded*

*Bottom left – Level 2 MEPs ongoing*


*Bottom right – Level 1 MEPs ongoing*

21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

9/1/2023



HANOVER