

# 21-600 HANOVER PINEHILLS II

---

Weekly Site Photos  
Week Ending

6/2/2023



## Sitework

*Building 2 flatwork near completion*

21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

6/2/2023



## Sitework

*Top left – Concrete Foundation at Building 2 BBQ grill #1*

*Top right – Concrete Foundation at Building 2 BBQ grill#2*

*Bottom left – Concrete Foundation at Building 2 firepit*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 2 Exterior

*Front elevation of Building 2*

21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

6/2/2023



## Building 2 Exterior

*Side entrance frame installed*

21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

6/2/2023



## Building 2 Exterior

*CMU infill at Building 2 elevator  
complete on all floors*

21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023



## Building 2 Exterior

*Exterior painting near completion*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023


## Building 2 Interior

*Top left – level 4 finish paint started*

*Top right – level 3 unit punch ongoing*

*Bottom left – level 2 finishes ongoing*

*Bottom right – level 1 cabinets installation started*



**21-600 Hanover Pinehills II**

**Weekly Site Photos**

**Week Ending**

**6/2/2023**

## Building 1 Exterior

*Top – Front exterior siding ongoing*

*Bottom - Clubhouse storefront frame installed with temp protection*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 1 Exterior

*Side Exterior looking from Building 2 – siding painting started*

21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

6/2/2023



## Building 1 Exterior

*Back of Building 1 Exterior - siding ongoing*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 1A Interior

*Top – level 4 doors/trim and baseboard ongoing*

*Bottom left – level 3 ceiling drywall started*

*Bottom right – level 2 MEP ongoing*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 1 Clubhouse Interior

*Top – Clubroom interior*

*Bottom – Lounge interior*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023

## Clubhouse

*Top - Lobby interior*

*Bottom – Leasing Center interior*



21-600 Hanover Pinehills II  
Weekly Site Photos  
Week Ending

6/2/2023

## Building 1B Interior

*Top left – level 4 MEP started*

*Top right – level 3 MEP started*

*Bottom left – level 2 MEP started*

*Bottom right – level 1 MEP started*



21-600 Hanover Pinehills II

Weekly Site Photos

Week Ending

6/2/2023

HANOVER