

Hanover Preston Hollow 20-584

# Weekly Project Photos



Project Photos for the Week of March 20th through March 24th, 2023.



Site overview, level 1 pour 3 poured 3/21.



Level 2 decking ongoing for level 2 pour 1.



West retaining wall forming and placement continuing North.



Temporary power distribution panel assembled, wire pulled to the tower crane.



Below-grade waterproofing complete on South retaining wall, backfill to grade.