



**Hanover Walnut Creek
Weekly Photos
Week Ending 3.24.2023**



Overhead Site View 3.24



Level 1&2 Corridors: Final Touch-Up Paint Near Complete



Level 3 Area 1: Hot Check & Construction Punch Ongoing



Level 2 Area 4: Management Walks Ongoing




Level 1&2: Unit Acceptance Walks Ongoing



Model Units: Furnished & Future Tenant Walks



Clubroom: Furnishings Complete; Building Inspection Near Complete



Leasing Lobby: Furnishings Complete; Management Team Preparing to Occupy



Tech Lounge: Furnishings Complete; Building Inspection Near Complete



Fitness: Furnishings Complete; Building Inspection Near Complete



Media Room: Furnishings Complete; Building Inspection Near Complete



Courtyard A: Pool Final Inspection Complete



Courtyard B: Building Inspection Near Complete



Loggia: Building Inspection Near Complete



Garage: Building Inspection Near Complete