

# 22-629 Hanover Stoneham

---

Weekly Site Photos  
Week Ending

9/1/2023



## Site

### *Overview of Site*

22-629 Hanover Stoneham

Weekly Site Photos  
Week Ending

8/18/2023



## Site

*Excavation at concrete box culvert completed. Coring scheduled for Tuesday.*

**22-629 Hanover Stoneham**

**Weekly Site Photos**  
**Week Ending**

**9/1/2023**



## Site

*Hammering ledge for retaining wall is complete. Crushed stone placement is ongoing.*

22-629 Hanover Stoneham

Weekly Site Photos  
Week Ending

9/1/2023



## Site

*Retaining Wall Install Ongoing*

22-629 Hanover Stoneham

Weekly Site Photos  
Week Ending

9/1/2023



## Garage

*North garage foundation wall poured,  
cured and stripped*

22-629 Hanover Stoneham

Weekly Site Photos  
Week Ending

9/1/2023



## Garage

*Last pour for the North garage foundation wall.*

22-629 Hanover Stoneham

Weekly Site Photos  
Week Ending

9/1/2023



## Garage

*Forming of West garage foundation  
footing complete.*

22-629 Hanover Stoneham

Weekly Site Photos  
Week Ending

9/1/2023



## Garage

*Excavating and prepping for South garage foundation footing nearing completion.*

22-629 Hanover Stoneham

Weekly Site Photos  
Week Ending

9/1/2023



HANOVER