

Weekly Site Photos



Week Ending
03.24.2023

Photo #000



Description: Ariel Project Photo.

Photo #001



Description: North Elevation of the Site – Exterior Tile/ Facade work in Progress.

Photo #002



Description: Northeast Elevation of Site – Exterior Work in Progress.

Photo #003



Description: East Elevation of the Site– Exterior Glazing and Elastomeric Coating in Progress.

Photo #004



Description: West Elevation of Site – Exterior Glazing in Progress.

Photo #005



Description: Window Wall Glazing Installation in progress on Level 23.

Photo #006



Description: Window Wall Glazing Installation Complete on Level 22.

Photo #007



Description: Unit Wall layout in Progress on Level 21.

Photo #008



Description: Unit Wall Framing in progress on Level 19.

Photo #009



Description: Level 16 Perimeter Wall Insulation & Pre Rock Complete.

Photo #010



Description: Level 10 City Inspections in progress.

Date: 03.24.2023

Photo #011



Description: Level 9 – Mockup Units Wood Flooring in Progress.

Photo #012



Description: Level 9 – Mockup Unit Kitchen Cabinets Installation in Progress.

Photo #013



Description: Level 9 – Mockup Tile Surrounds Complete.

Photo #014



Description: Shaft Walls in Progress on Level 18.

Photo #015



Description: Metal Stair Railing Installation in Progress.

Photo #016



Description: Level 6 Amenity – Pre Rock in Progress.

Photo #017



Description: Level 1 Lobby Design Team Box Walk Complete.

Photo #018



Description: Elastomeric Coating in Progress on East Elevation.