

19-570
HANOVER
BRAZOS
STREET

Weekly Site Photos
Week Ending
6/2/2023



Level 44 & 45 Exterior

Exterior sheathing and rain screen in progress.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 45

Amenity area box walk in progress.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 44

Amenity area box walk in progress.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 43

Corridor drywall install complete.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 41

Unit drywall tape and float in progress.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 41

Stairwell lighting and fire safety trim-out complete up to level 41.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 21

Management 1st walks in progress.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 19

Management back-walks in progress.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Level 1 Exterior - West

Garage entry framing in progress.

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023




Level 1 Exterior - North

North elevation curb and gutter, sidewalk, and paver sub-slab complete.



Retail field tile installation beginning.



19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023

North and West Elevation Overall View

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



South and West Elevation
Overall View

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



Aerial View

19-570 Hanover Brazos Street
Weekly Site Photos
Week Ending
6/2/2023



HANOVER