



21-590 Hanover South End

Ariel Photo East

21-590 Hanover South End
Weekly Site Photos
Week Ending

5/26/2023



HANOVER
COMPANY

Hanover South End

Image # 75
Date : 05.17.2023
Aero Photo 888.542.0231

Northeast – Area A, Levels 3 & 4

-Level 4 complete. Level 5 framing in progress.

-Mold prevention spray in progress on levels 3 and 4

21-590 Hanover South End
Weekly Site Photos
Week Ending

5/26/2023



Northwest/West perimeter – Area D

-Level 5 walls installation in progress on Dunavant St.

-Level 6 trusses installation in progress in D

21-590 Hanover South End

Weekly Site Photos

Week Ending



5/26/2023



Southwest - Area C2, Level 3

-Rebar, PT cable installation.

-C2, Level 3 elevated deck
installation complete.




21-590 Hanover South End
Weekly Site Photos
Week Ending

5/26/2023

East – Area B

- Stair Tower B lift 4 in progress
- Elevator G3 3rd lift grout pour in progress
- Sandbox inspection scheduled



21-590 Hanover South End
Weekly Site Photos
Week Ending

5/26/2023

Courtyard/ Framing

*-Courtyard exterior framing levels 3-5
in progress*

*-Framing corridors levels 5 buildings
A&D in progress*



21-590 Hanover South End
Weekly Site Photos
Week Ending

5/26/2023

Street Views (S Tryon St)

-S Tryon St viewing east exterior sheathing complete levels 3&4

-Level 6 floor trusses installation in progress

21-590 Hanover South End

Weekly Site Photos

Week Ending

5/26/2023



Street Views (Dunavant St.)

-Exterior sheathing completed levels 3-4

-Exterior walls completed level 5

21-590 Hanover South End

Weekly Site Photos

Week Ending

5/26/2023



HANOVER