

21-596 Hanover Laguna Niguel

Weekly Site Photos
Week Ending
9/01/2023



Construction Operations

*Birds Eye View of Construction
Operations*

21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending
9/01/2023



Unit Mockup

Rough Complete

21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending
9/01/2023



Stair 5 Install

Stair 5 Install Complete

21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending
9/01/2023



Residential – Area 3

Area 3 Concrete Pour Complete

21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending
9/01/2023



Southwest Elevation Overview

*Overview of construction operations
and scaffolding*

21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending
9/01/2023



Roof A1/2

A1 & A2 Insulation Installation ongoing



21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending

9/01/2023

Amenity – Level 1

Amenity Box Walk Complete

21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending
9/01/2023



Phasing Plan

Reference Sequencing/ callouts for prior slides



21 – 596 Hanover Laguna Niguel
Weekly Site Photos
Week Ending
9/01/2023

HANOVER