

20-581
HANOVER
COLONY
PLACE

Weekly Site Photos
Week Ending
9/01/2023



Building 1

Front Entrance

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
9/01/2023



Building 2

Level 4 Top Left – Management Walks Complete

Level 3 Top Right – Management Walks Complete

Level 2 Bottom Left – Management Walks Nearing Completion

Level 1 Bottom Right – Management Walks In Progress



20-581 Hanover Colony Place
Weekly Site Photos
Week Ending

9/01/2023

Building 2

Overall View

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending
9/01/2023



Building 3

Level 4 Top Left – Finishes Nearing Completion


Level 3 Top Right – Finishes Nearing Completion, Awaiting Appliances

Level 2 Bottom Left – Countertops Complete, Backsplash Commenced

Level 1 Bottom Right – Flooring Install Complete

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending

9/01/2023



Building 3

Overall View

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending

9/01/2023



Building 4

*Level 4 Top Left – Cabinet Install
Nearing Completion*

*Level 3 Top Right – Unit Tape &
Mud Complete, Gypcrete Poured*

*Level 2 Bottom Left – Sheetrock Install
Nearing Completion*

*Level 1 Bottom Right – MEP's
Nearing Completion*

**20-581 Hanover Colony Place
Weekly Site Photos
Week Ending**

9/01/2023



Building 4

Overall View

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending

9/01/2023



Courtyard Progress

View From Building 1 Roof.

20-581 Hanover Colony Place
Weekly Site Photos
Week Ending

9/01/2023



Sitework

Top Left – Front Entry Post Caps Installed

Top Right – Northside of Phase 2 Binder

Bottom Left – Courtyard Sod Installed

Bottom Right – Pool Enclosure Glass Installed

**20-581 Hanover Colony Place
Weekly Site Photos
Week Ending**

9/01/2023



HANOVER