

21-592

Hanover Edgewood

Weekly Site Photos
Week Ending
5/19/2023



Site Overview

21-592 HANOVER EDGEWOOD
Weekly Site Photos
Week Ending
5/19/2023



Parking Garage

Pre-cast garage erection is complete.

Joint grouting has begun.



21-592 HANOVER EDGEWOOD
Weekly Site Photos
Week Ending
5/19/2023



Courtyard 1 West Level 2 Units

*Slab on grade complete. Ready for
phase 1, level 3 elevated deck shoring
and formwork.*

21-592 HANOVER EDGEWOOD
Weekly Site Photos
Week Ending
5/19/2023



Courtyard 1 North Level 2 Units

Slab on grade ready for concrete pour.

21-592 HANOVER EDGEWOOD
Weekly Site Photos
Week Ending
5/19/2023



Amenity

Level 2 amenity area columns, shear walls, and foundations walls are ongoing.



21-592 HANOVER EDGEWOOD
Weekly Site Photos
Week Ending
5/19/2023

Level 3 Retail Area

*Forming and reinforcement placement
for retail columns and shear walls.*

*Backfill for underground rough-in is
in progress.*

21-592 HANOVER EDGEWOOD
Weekly Site Photos
Week Ending
5/19/2023



HANOVER