

20-585
HANOVER
WEYMOUTH

Weekly Site Photos
Week Ending
6/2/2023



OVERALL SITE

Site entrance from Washington St.

20-585 HANOVER WEYMOUTH

Weekly Site Photos

Week Ending

6/2/2023



Building 1

*Wall Panels, Trusses, and Sheathing
Installation at Level 1 Units
Complete*

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending
6/2/2023



Building 1

*Wall Panel Installation at Level 2
Units Ongoing*

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending
6/2/2023



Building 1

Level 2 Slab on Grade Complete

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending
6/2/2023



Building 1

*Intumescent Paint at Clubhouse Steel
Ongoing*



20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending
6/2/2023



Mail Building

Wall Panels Installed. Trusses Ongoing

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending

6/2/2023



Garage B

Backfill Foundations Complete

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending
6/2/2023



Garage C

Excavate and Prep For Footings

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending
6/2/2023



Garage D

Footings Complete. Forming Foundation Walls

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending

6/2/2023



BUILDING 2

Underground Plumbing Ongoing

20-585 HANOVER WEYMOUTH
Weekly Site Photos
Week Ending
6/2/2023



BUILDING 2

Elevator 2B shaft complete

20-585 HANOVER WEYMOUTH

Weekly Site Photos

Week Ending

6/2/2023



Overall Site

*Electrical Ductbank to Transformer
2 Ongoing*



20-585 HANOVER WEYMOUTH

Weekly Site Photos

Week Ending

6/2/2023

HANOVER